

BRANZ Bulletin Index
1 August 2021

Titles in **Bold** are current Bulletins

Titles in *Italics* indicate Bulletins that have been withdrawn

All current bulletins are available as a print document, a PDF file and as an epub; when noted PDF only, no print copy is available

nr = bulletin withdrawn, no replacement

(RXXX) refers to the bulletin the title replaced

red = changes in this version of the index

No.	Issued	New Number	Title	
1	-1959		<i>New Materials a Cautionary Tale</i>	<i>withdrawn</i>
2	-1959	refer 286	<i>Aluminium Window Frames</i>	<i>withdrawn</i>
3	(1959, 66)		<i>Use of Radiata Pine in Construction (The)</i>	<i>withdrawn</i>
4	-1966		<i>Aids to Concreting</i>	<i>withdrawn</i>
5	-1966		<i>Fire Hazards with Slow Combustion Stove Installation</i>	<i>withdrawn</i>
6	-1960	refer 175	<i>Timber Preservation for the User</i>	<i>withdrawn</i>
7	(1960, 66)	refer 273	<i>Clear Finishes for External Timberwork</i>	<i>withdrawn</i>
8	-1960	refer 155	<i>Waterproof Building Papers</i>	<i>withdrawn</i>
9	(1960, 66)	refer 214	<i>Galvanised Corrugated Roofing Iron</i>	<i>withdrawn</i>
10	-1960	refer 224	<i>Double Windows</i>	<i>withdrawn</i>
11	-1960	refer 225	<i>Glazing into Aluminium</i>	<i>withdrawn</i>
12	(1960, 66)	refer 140	<i>Spouting and Downpiping</i>	<i>withdrawn</i>
13	-1960		<i>Fire Protection of Buildings</i>	<i>withdrawn</i>
14	(1960, 66)	refer 206	<i>Paint Protection of Iron and Steel against Corrosion</i>	<i>withdrawn</i>
15	-1960	refer 215	<i>Dampness in Buildings</i>	<i>withdrawn</i>
16	(1960, 66)	refer 217	<i>Thermal Insulation for Buildings</i>	<i>withdrawn</i>
17	(1960, 77)	refer 237	<i>Dry Rot in Timber</i>	<i>withdrawn</i>
18	(1961, 66)	refer 191	<i>Beware of the Wind</i>	<i>withdrawn</i>
19	-1966		<i>Good Concrete for the Small Builder</i>	<i>withdrawn</i>
20	(1961, 66)		<i>Present Day Paint and its Use</i>	<i>withdrawn</i>
21	-1961		<i>Finishing of Concrete Floors (The)</i>	<i>withdrawn</i>
22	-1961	refer 35	<i>Safe Glazing Sizes in High Wind</i>	<i>withdrawn</i>
23	(1961, 66)	refer 274	<i>Dampproof Membranes to Concrete Slabs</i>	<i>withdrawn</i>
24	-1961	refer 79	<i>Electric Floor Heating</i>	<i>withdrawn</i>
25	(1961, 66)	refer 271	<i>Changes in the Moisture Content of Timber</i>	<i>withdrawn</i>
26	(1961, 66)	refer 92	<i>Floor Coverings on Concrete Slabs</i>	<i>withdrawn</i>
27	(1961, 77)		<i>Domestic Electric Power Supply</i>	<i>withdrawn</i>
28	-1961		<i>Building Research in Australia</i>	<i>withdrawn</i>
29	-1961	refer 132	<i>Sound Insulating Partitions in Buildings</i>	<i>withdrawn</i>
30	-1962		<i>Building Materials and Fire</i>	<i>withdrawn</i>
31	(1962, 66)		<i>Plastic Formwork for Concrete</i>	<i>withdrawn</i>
32	-1962	refer 268	<i>Efflorescence of Masonry</i>	<i>withdrawn</i>
33	-1962	refer 142	<i>Masonry Veneer Construction</i>	<i>withdrawn</i>
34	-1962		<i>Warm Air Curtains</i>	<i>withdrawn</i>
35	-1962		<i>Recommended Glazing Sizes in High Winds (R22)</i>	<i>withdrawn</i>
36	-1962	refer 231	<i>Repairing Cracks in Concrete</i>	<i>withdrawn</i>
37	(1962, 66)	refer 290	<i>Waterproofing of Basements (Tanking) - 1</i>	<i>withdrawn</i>
38	(1962, 66)	refer 291	<i>Waterproofing of Basements (Tanking) - 2</i>	<i>withdrawn</i>
39	-1962	refer 145, 147	<i>Plastering on Concrete</i>	<i>withdrawn</i>
40	-1962	refer 143	<i>Good Lighting in Buildings</i>	<i>withdrawn</i>
41	(1962, 66)		<i>Mis-use of Metals in Buildings: Corrosion (The)</i>	<i>withdrawn</i>
42	(1963, 66)		<i>Plumbing for Tall Buildings</i>	<i>withdrawn</i>
43	-1963		<i>Permanent Supplementary Lighting in Offices</i>	<i>withdrawn</i>
44	(1963, 66)		<i>Formwork for Concreting</i>	<i>withdrawn</i>
45	(1963, 66)		<i>Fair Face Finish to Concrete</i>	<i>withdrawn</i>
46	(1963, 66)		<i>Built-up Roofing</i>	<i>withdrawn</i>
47	-1963		<i>Noise Control Within a Room</i>	<i>withdrawn</i>
48	-1963		<i>House Foundations on Unstable Soil</i>	<i>withdrawn</i>
49	-1963	refer 260	<i>Exposed Aggregate Facing Panels</i>	<i>withdrawn</i>
50	(1963, 66)		<i>Model Building Bylaw (The)</i>	<i>withdrawn</i>
51	-1963		<i>Do's and Don'ts</i>	<i>withdrawn</i>
52	-1963		<i>Silicone Water Repellents</i>	<i>withdrawn</i>
53	-1963		<i>Wood Screws</i>	<i>withdrawn</i>

BRANZ Bulletin Index
1 August 2021

No.	Issued	New Number	Title	
54	-1964		Electric Wiring Regulations 1961	withdrawn
55	-1964		Metal Roofing Systems	withdrawn
56	-1964		Trade Literature for the Building Industry: Its Classification and Storage	withdrawn
57	-1964		Do's and Don'ts No 2	withdrawn
58	-1964	refer 316	Timber Flooring	withdrawn
59	-1964	refer 269	Curing of Concrete (The)	withdrawn
60	-1964		Isolating Transformers	withdrawn
61	-1964		Roof Vents for the Control of Fire	withdrawn
62	-1964		Wire Nails for Building Purposes	withdrawn
63	-1964		Design of Modern Kitchens (The)	withdrawn
64	-1964	refer 246	Adhesives for the Building Industry	withdrawn
65	-1964		Sound Insulating Floors in Buildings - 1	withdrawn
66	-1965		Concrete Admixtures	withdrawn
67	-1965	refer 437	Mould in Dwellings	withdrawn 1/06/2003
68	-1965		Mould Stains on Timber	withdrawn
69	-1965	refer 94	Damp-Course for Masonry Walls (A)	withdrawn
70	-1965	refer 285	Dimensional Changes in Building Materials	withdrawn
71	-1965	refer 182	Thermal Insulation of Houses	withdrawn
72	-1965		Do's and Don'ts No 3	withdrawn
73	-1965	refer 220, 221	Ceramic Tiled Floors	withdrawn
74	-1965		Mastics and Gaskets	withdrawn
75	-1965	refer 359	Rain Penetration	withdrawn
76	-1965		Uses of Lime in Buildings - 1 (The)	withdrawn
77	-1965		Uses of Lime in Buildings - 2 (The)	withdrawn
78	-1966		Do's and Don'ts No 4	withdrawn
79	-1966	refer 293	Electric Floor Heating – 2 (R24)	withdrawn
80	-1966	refer 230	Stainless Steel for Buildings	withdrawn
81	-1966		Behaviour of Curtain Walling in Fire (The)	withdrawn
82	-1966		Internal Wood Flooring Naturally Finished	withdrawn
83	-1966	refer 331	Practical Noise Control for Timber Framed Buildings	withdrawn
84	-1966		Do's and Don'ts No 5	withdrawn
85	-1966		House Construction - Critical Path Planning	withdrawn
86	-1966		Lightweight Concrete 1 - Aerated Concrete	withdrawn
87	-1966	refer 299, 300	Unplasticised PVC Pipe	withdrawn
88	-1966		Lightweight Concrete 2 - Pumice Concrete	withdrawn
89	-1966		Battery Casting of Concrete Panels	withdrawn
90	-1967		Do's and Don'ts No 6	withdrawn
91	-1967		Solar Radiation Through Vertical Glass	withdrawn
92	-1967	refer 222,223	PVC Flooring (R22)	withdrawn
93	-1967		Glazing Design	withdrawn
94	(1967, 77)	refer 142	Cavity Wall Construction	withdrawn
95	-1967		Weatherproof Jointing	withdrawn
96	-1967		Lightweight Concrete 3 No-fines Concrete	withdrawn
97	-1967		Lightweight Concrete 4 Artificial Aggregates - Vermiculite	withdrawn
98	-1967		Gypsum Products - Their Behaviour in Fire	withdrawn
99	-1967		Lightweight Concrete 5 Artificial Aggregates - Perlite	withdrawn
100	(1967, 77)		Availability of Daylight for Building Design	withdrawn
101	-1967		Lightweight Concrete 6 - Sawdust Concrete	withdrawn
102	-1968		Solar Water Heating for Domestic Use	withdrawn
103	-1968		Airflow Around Buildings	withdrawn
104	-1968		Sources of Electric Light	withdrawn
105	-1968		Pitched Roofs Performance Requirements	withdrawn
106	-1968		Accuracy and Tolerances - Part 1	withdrawn
107	-1968		Accuracy and Tolerances - Part 2	withdrawn
108	-1968		Accuracy and Tolerances - Part 3	withdrawn
109	-1968	refer 216	Condensation	withdrawn
110	-1968		Vapour Diffusion	withdrawn
111	(1968, 77)	refer 302	Flat Compact Roofs - Problems	withdrawn
112	(1968, 77)	refer 302	Flat Compact Roofs - Practice	withdrawn

BRANZ Bulletin Index
1 August 2021

No.	Issued	New Number	Title	
113	-1968	refer 302	<i>Sloping Compact Roofs</i>	<i>withdrawn</i>
114	-1969	refer 216	<i>Risk of Condensation (The) (R109)</i>	<i>withdrawn</i>
115	-1969		<i>Organic Surface Coatings</i>	<i>withdrawn</i>
116	-1969		<i>Masonry Cladding</i>	<i>withdrawn</i>
117	-1969		<i>Metric System (The)</i>	<i>withdrawn</i>
118	-1969	refer 176	<i>Particle Board Flooring</i>	<i>withdrawn</i>
119	-1969		<i>Recommendations for the Painting of Buildings</i>	<i>withdrawn</i>
120	-1969		<i>Thermal Resistance</i>	<i>withdrawn</i>
121	-1969	refer 249	<i>Metal Hardware Finishes</i>	<i>withdrawn</i>
122	-1969	refer 219	<i>Single Stack Drainage</i>	<i>withdrawn</i>
123	-1969	refer 360	<i>Level Surfaces on Concrete Floors under Thin Flooring</i>	<i>withdrawn 1/08/1997</i>
124	-1969		<i>Fire Resistance Ratings</i>	<i>withdrawn</i>
125	-1969	refer 277	<i>Vapour Barriers</i>	<i>withdrawn</i>
126	-1970		<i>External Walls: Principles and Practice</i>	<i>withdrawn</i>
127	-1970		<i>Concrete Blocks for Houses</i>	<i>withdrawn</i>
128	-1970		<i>Continuity of Publication</i>	<i>withdrawn</i>
129	-1970		<i>Timber Shrinkage in New Buildings</i>	<i>withdrawn</i>
130	(1970, 77)	refer 295	<i>Specifying Timber - Species and Grade</i>	<i>withdrawn</i>
131	-1970		<i>Care of Materials on Site</i>	<i>withdrawn</i>
132	-1970		<i>Acoustic Insulation Properties of Partitions in Buildings</i>	<i>withdrawn</i>
133	-1970		<i>CPM fro Building and Construction Management</i>	<i>withdrawn</i>
134	-1970		<i>CPM: Building and Construction Some Useful Developments</i>	<i>withdrawn</i>
135	-1970		<i>Wind Loads: Some Problem and Design Aspects</i>	<i>withdrawn</i>
136	-1970		<i>Surface Spread of Flame</i>	<i>withdrawn</i>
137	-1970		<i>Metric Conversion</i>	<i>withdrawn</i>
138	-1971		<i>Metric Conversion</i>	<i>withdrawn</i>
139	-1971		<i>Concrete Floor Finishes and Toppings</i>	<i>withdrawn</i>
140	-1971	refer 251	<i>Gutters Spouting and Downpipes</i>	<i>withdrawn</i>
141	-1971	refer 204	<i>CI/SfB Information Classification System</i>	<i>withdrawn</i>
142	-1971	refer 324	<i>Masonry Veneer Construction</i>	<i>withdrawn</i>
143	-1971		<i>Good Lighting in Buildings</i>	<i>withdrawn</i>
144	-1971		<i>Do's and Don'ts No 7</i>	<i>withdrawn</i>
145	-1971		<i>Plastering 1 - General Practices and Problems</i>	<i>withdrawn</i>
146	-1971	refer 214	<i>Galvanised Corrugated Steel and its Protection</i>	<i>withdrawn</i>
147	-1971		<i>Plastering 2 - External Walls</i>	<i>withdrawn</i>
148	-1971		<i>How to Keep Comfortable in Buildings</i>	<i>withdrawn</i>
149	-1971	refer 279	<i>Powder-Powered Tools</i>	<i>withdrawn</i>
150	-1972		<i>Building Bylaws and Regulations</i>	<i>withdrawn</i>
151	-1972		<i>Timber Formwork for Concrete</i>	<i>withdrawn</i>
152	(1972, 77)		<i>Concrete Ground Floor Slabs</i>	<i>withdrawn</i>
153	-1972		<i>Design for Mass Housing</i>	<i>withdrawn</i>
154	(1972, 80)		<i>Plastering (3) Internal Walls and Ceilings</i>	<i>withdrawn</i>
155	-1972	refer 277	<i>Building Papers and Membranes</i>	<i>withdrawn</i>
156	-1972		<i>Change to Metric in the Building Industry</i>	<i>withdrawn</i>
157	(1972, 78)	refer 238	<i>Putties Mastics and Sealants 1</i>	<i>withdrawn</i>
158	(1972, 78)	refer 239	<i>Putties Mastics and Sealants 2</i>	<i>withdrawn</i>
159	-1972		<i>Pumping Concrete</i>	<i>withdrawn</i>
160	-1972		<i>Index to Bulletins</i>	<i>withdrawn</i>
161	(1972, 80)		<i>Formwork Release Agents</i>	<i>withdrawn</i>
162	-1973		<i>Joists, Floor Beams and Lintels for Small Buildings</i>	<i>withdrawn</i>
163	(1973, 78)		<i>Sound Absorbers and their Use</i>	<i>withdrawn</i>
164	-1973		<i>Cost of Labour (The)</i>	<i>withdrawn</i>
165	-1973		<i>On-Site Precasting - Tilt up Part 1</i>	<i>withdrawn</i>
166	-1973		<i>On-Site Precasting - Tilt up Part 2</i>	<i>withdrawn</i>
167	-1973		<i>Corrosion of Copper Pipe in Housing</i>	<i>withdrawn</i>
168	-1973		<i>Squeaky Floors</i>	<i>withdrawn</i>
169	-1973	refer 292	<i>Correct Use of Foil Insulation in Walls (The)</i>	<i>withdrawn</i>
170	-1973	refer 316	<i>Timber Vertical Boarding</i>	<i>withdrawn</i>
171	-1973		<i>Stainless Steel Water Tanks</i>	<i>withdrawn</i>
172	-1973		<i>Plywood Flooring</i>	<i>withdrawn</i>

BRANZ Bulletin Index
1 August 2021

No.	Issued	New Number	Title	
173	-1973		Falls on Building Sites	withdrawn
174	-1974		Metrication 3	withdrawn
175	-1974	refer 275	Timber Preservation for the User	withdrawn
176	-1974	refer 294	Particle Board Flooring	withdrawn
177	-1975	refer 233	Building Foil Insulated Floors	withdrawn
178	-1975		Do's and Don'ts	withdrawn
179	-1975	refer 293	Embedded Electric Floor Heating (R79)	withdrawn
180	(1975, 78)	refer 331	Acoustic Performance Requirements of Partitions	withdrawn
181	-1975		Control of Shower Temperature Fluctuations	withdrawn
182	-1976	refer 217	Thermal Insulation of Houses	withdrawn
183	(1976,79)		Plumbing Do's and Don'ts	withdrawn
184	-1976	refer 227	Weights and Sizes of Building Materials	withdrawn
185	-1976		Index to Bulletins	withdrawn
186	-1976		Case Histories	withdrawn
187	-1976		Storm Damage	withdrawn
188	-1976	refer 265	Solar Control Glass Installation Practice	withdrawn
189	(1976, 79)	refer 215	Moisture Control in Buildings	withdrawn
190	-1976		Solar Control Glass Case Histories	withdrawn
191	(1976, 81)	refer 321	Wind - Selecting and Protecting a Site (R16)	withdrawn
192	-1977	refer 327	Open Fireplaces and Chimneys	withdrawn
193	(1976, 79)		Fireside Topics	withdrawn
194	-1977		Weather and the Builder	withdrawn
195	-1977	refer 207	Building on Windswept Sites	withdrawn
196	(1977, 79)		Solar Water Heaters Application	withdrawn
197	-1977	refer 197A	Solar Water Heaters Installation	withdrawn
197A	-1977	refer 197B	Solar Water Heaters Installation	withdrawn
197B	-1977		Solar Water Heaters Installation	withdrawn
198	-1977		Fire and Buildings - Terminology and tests	withdrawn
199	-1977		Case Histories	withdrawn
200	-1977	refer 307	Fire and Buildings - Control of Fire by Building Design	withdrawn
201	-1977	refer 334	Reducing Heat Losses From Existing Houses	withdrawn
202	-1978	refer 254	Avoiding Corrosion Problems in Buildings	withdrawn
203	-1978	refer 332	Atmospheric Corrosion of Metals	withdrawn
204	-1978		CI/SfB Information Classification System	withdrawn
205	(1978, 84)		Concrete Do's and Don'ts	withdrawn
206	-1978	refer 232	Pole Frame Construction	withdrawn
207	-1978	refer 325	Building on Windswept Sites	withdrawn
208	-1978	refer 257	Wood Primers	withdrawn
209	-1978		Management Assistance for Small Companies	withdrawn
210	-1978	refer 331	Noise Control in Flats - 1	withdrawn
211	-1978	refer 331	Noise Control in Flats - 2	withdrawn
212	-1979	refer 438	Soil Testing (with the Scala Penetrometer)	withdrawn 1/08/2003
213	-1979	refer 349	Use of Anodised Aluminium	withdrawn 1/08/1996
214	-1979		Protection of Galvanised Steel Claddings	withdrawn
215	(1979	refer 272	Moisture Control in Buildings	withdrawn
216	-1979	refer 272	Condensation (R109)	withdrawn
217	(1979, 81)	refer 292	Thermal Insulation of Houses	withdrawn
218	(1979, 84)	refer 349	Use of Powder-coated Aluminium	withdrawn 1/08/1996
219	-1980		Single Stack Drainage	withdrawn
220	-1980	refer Good Tiling Pra	Ceramic Tiled Floors - (1) Materials and Maintenance (R73)	withdrawn
221	-1980	refer Good Tiling Pra	Ceramic Tiled Floors - (2) Laying (R 73)	withdrawn
222	-1980	refer 329	PVC Flooring 1 - Materials and Maintenance (R 92)	withdrawn
223	-1980	refer 330	PVC Flooring 2 Preparation and Laying (R 92)	withdrawn
224	-1980	refer 312	Double Glazing	withdrawn
225	-1981	refer 286	Aluminium Windows Do's and Don'ts	withdrawn
226	-1981	refer 351	Corrosion of Reinforcing Steel	withdrawn 1/12/1996
227	-1981		Weights and Sizes of Building Materials	withdrawn
228	-1981		Glass Fibre-reinforced Polyester Cladding Panels 1 Materials and Manufacture	withdrawn

BRANZ Bulletin Index
1 August 2021

No.	Issued	New Number	Title	
229	-1981		Glass Fibre-reinforced Polyester Cladding Panels 2 Design, Durability and Maintenance	withdrawn
230	-1982		Stainless Steels for Building Claddings	withdrawn
231	-1982	refer 363	Repairing Cracks in Concrete (R36)	withdrawn 1/01/1998
232	-1989	refer 352	Pole House Construction (1989)	withdrawn 1/12/1996
233	-1983	refer 292	Insulating Suspended Timber Frame Floors	withdrawn
234	-1983	refer 261	Coil-Coated Products: Information for Designers	withdrawn
235	-1984	refer 358	Nail Fixing of Corrugated Steel Roofing	withdrawn 1/06/1997
236	-1984	refer 337	Corrosion and Staining of Glass Windows	withdrawn
237	-1984	refer 338	Dry Rot in Timber (R17)	withdrawn
238	-1984	refer 283	Sealed Joints in External Claddings 1 Joint Design	withdrawn
239	-1984	refer 284	Sealed Joints in External Claddings 2 - Sealants	withdrawn
240	-1984	refer 308	Restoring a House after Flood Damage	withdrawn
241	-1985	refer 322	Glazing Plastics 1: Types and Durability	withdrawn
242	-1985	refer 323	Glazing Plastics 2: Design and Fixing	withdrawn
243	-1985	refer 278	Preventing Dampness in Houses 1: Underfloor Dampness	withdrawn
244	-1985	refer 278	Preventing Dampness in Houses 2: Condensation and Mildew (R216)	withdrawn
245	-1985	refer 319	Subfloor Ventilation	withdrawn
246	-1985	refer 356	Adhesives for Use with Wood and Wood-based Products	withdrawn 1/06/1997
247	(1985, 86)		Solid Fuel Stoves	withdrawn
248	-1986		Solid Fuel Appliances: Their Use in Existing Fireplaces	withdrawn
249	-1986	Refer 362	Finishes on Architectural Hardware	withdrawn 1/10/1997
250	-1986		Testing for Fire Resistance	withdrawn
251	-1986	refer 350	Gutters and Downpipes (R140)	withdrawn 1/10/1996
252	-1987	refer 348	Domestic Smoke Alarms	withdrawn 1/07/1996
253	-1987	refer 377	Maintenance Painting of Coated Steel Structures	withdrawn 1/11/1998
254	-1987	refer 332	Avoiding Corrosion Problems in Buildings	withdrawn
255	-1987		Polymer Concrete Floors	withdrawn
256		refer 320	Stair Design and Safety	withdrawn
257	-1987	refer 315	Wood Primers	withdrawn
258	-1987	refer 444	Lessons From the 1987 Edgcombe Earthquake	withdrawn 1/12/2003
259	-1988	refer 306	Inspection Procedures for Chimneys, Fireplaces and Solid Fuel Burning Appliances	withdrawn
260	-1988	refer 335	Exposed Aggregate Precast Concrete Panels	withdrawn
261	-1989	refer 317	Coil-Coated Metal Claddings	withdrawn
262	-1989	refer 376	Residential Fire Sprinklers	withdrawn 1/09/1998
263	-1989	refer 318	Care of Coil-Coated Metal Claddings	withdrawn
264	-1989	refer 297	Solar Control Glass - Types and Properties	withdrawn
265	-1989	refer 298	Solar Control Glass - Design and Installation Practice	withdrawn
266	-1989	refer Good Tiling Practice	Exterior Ceramic Wall Tiling	withdrawn
267	-1989	refer 399	Timber Pile Foundations for Single Storey Light Timber Framed Buildings	withdrawn 1/05/2000
268	-1990	refer 442	Efflorescence on Masonry (R32)	withdrawn 1/12/2003
269	-1990	refer 382	Curing of Concrete (The) (R 59)	withdrawn 1/03/1999
270	-1990		Human Impact on Glass in High Rise Buildings	withdrawn
271	-1990	refer 343	Changes in Moisture Content in Timber (R 25)	withdrawn 1/04/1996
272	-1990	refer 359, 379	Moisture in the Building Structure (R 215)	withdrawn 1/08/1997
273	-1990	refer 296	Transparent and Semi-transparent Exterior Finishes for Timber Exposed to the Weather (R 273)	withdrawn??92
274	-1990	refer 333	Damp-proof Membranes to Concrete Slabs	withdrawn?? 95
275	-1990	refer 386	Timber Treatment for Users and Specifiers (R 175)	withdrawn 1/05/1999
276	-1991	refer 340	Conservatories	withdrawn 1/02/1996
277	-1991	refer 336	Building Papers, Vapour Barriers and Wind Barriers (R125, 155)	withdrawn 1/08/1995
278	-1991	refer 367	Preventing Dampness in Houses (R 243, 244)	withdrawn 1/03/1998
279	-1991	refer 393	Powder-Powered Fastening Devices (R 149)	withdrawn 1/11/1999
280	-1991	refer 361	Weathergrooves	withdrawn 1/10/1997
281	-1991		Glass Blocks - Selection and Design	withdrawn nr

**BRANZ Bulletin Index
1 August 2021**

No.	Issued	New Number	Title	
282	-1991		<i>Glass Blocks - Materials and Installation</i>	<i>withdrawn nr</i>
283	-1991	refer 440	<i>Sealed Joints in External Claddings - (1) Joint Design (R 238)</i>	<i>withdrawn 1/10/2003</i>
284	-1991	refer 441	<i>Sealed Joints in External Claddings - (2) Sealants (R 239)</i>	<i>withdrawn 1/10/2003</i>
285	-1991	refer 418	<i>Designing for Thermal and Moisture Movement (R 70)</i>	<i>withdrawn 1/07/2001</i>
286	-1991	refer 422	<i>Aluminium Windows – Design, Handling and Maintenance (R 225)</i>	<i>withdrawn 1/02/2002</i>
287	-1991	refer 342	<i>External Insulation and Finish Systems</i>	<i>withdrawn 1/02/1996</i>
288	-1992		<i>Timber Shingle and Shake Roofing</i>	<i>withdrawn 1/12/2003</i>
289	-1992	refer 385	<i>Asphalt Shingle Roofing</i>	<i>withdrawn 1/05/1999</i>
290	-1992	refer 397	<i>Basement Waterproofing - Design Principles (R 37)</i>	<i>withdrawn 1/03/2000</i>
291	-1992	refer 397	<i>Basement Waterproofing - Selecting An Appropriate Membrane (R 38)</i>	<i>withdrawn 1/03/2000</i>
292	-1992	refer 357	<i>Thermal Insulation of Houses (R 169, 217, 233)</i>	<i>withdrawn 1/06/1997</i>
293	-1992	refer 344	<i>Embedded Electric Floor Heating (R 179)</i>	<i>withdrawn 1/04/1996</i>
294	-1992	refer 371	<i>Reconstituted Wood Board Sheet Flooring</i>	<i>withdrawn 1/05/1998</i>
295	-1992	refer 373	<i>Specifying Timber (R 130)</i>	<i>withdrawn 1/07/1998</i>
296	-1992		<i>Transparent and Semi-transparent Exterior Finishes for Timber Exposed to the Weather (R 273)</i>	<i>withdrawn nr</i>
297	-1992	refer 450	<i>Solar Control Glass - Types and Properties (R 264)</i>	<i>withdrawn 1/06/2004</i>
298	-1992	refer 450	<i>Solar Control Glass - Design and Installation Practice (R 265)</i>	<i>withdrawn 1/06/2004</i>
299	-1992		<i>Plastic Piping - Types and Properties</i>	<i>withdrawn nr</i>
300	-1992		<i>Plastic Piping - Installation</i>	<i>withdrawn nr</i>
301	-1993	refer GPG Internal Linings	<i>Preventing Peaking and Popping Problems with Gypsum Plaster Board</i>	<i>withdrawn 19/6/2107</i>
302	-1992	refer 368	<i>Constructing Timber Framed Skillion Roofs (R 111, 112, 113)</i>	<i>withdrawn 1/03/1998</i>
303	-1992	refer 460	<i>Moisture Control in Recreational Facilities</i>	<i>withdrawn 1/04/2005</i>
304	-1993	refer 467	<i>Flashing Design</i>	<i>withdrawn 1/12/2005</i>
305	-1993	refer 448	<i>Domestic Flashing Installation</i>	<i>withdrawn 1/04/2004</i>
306	-1993	refer 654	<i>Inspection Procedures for Chimneys, Fireplaces and Solid Fuel Appliances (R259)</i>	<i>withdrawn 1/10/2020</i>
307	-1993	refer 420	<i>Designing for Fire Safety (R 200)</i>	<i>withdrawn 1/09/2001</i>
308	-1993	refer 455	<i>Restoring a House After Flood Damage (R240)</i>	<i>withdrawn 1/11/2004</i>
309	-1993	refer 420	<i>Fire Safety in Dwellings</i>	<i>withdrawn 1/09/2001</i>
310	not issued			
311	-1993	Refer 540	<i>Use and Control of Solar Gain</i>	<i>withdrawn 1/10/2011</i>
312	-1993	pdf only	<i>Reducing Heat Loss Through Windows. (R 224)</i>	<i>withdrawn</i>
313	-1993	refer 605	<i>Domestic Glazing Safety</i>	<i>withdrawn 1/12/2016</i>
314	-1993	refer 633	<i>Removing Paint From Houses</i>	<i>withdrawn 1/02/2019</i>
315	-1993		<i>Wood Primers (R 257)</i>	<i>withdrawn nr</i>
316	-1993		<i>Timber Strip Flooring and Internal Linings (R 170)</i>	<i>withdrawn nr</i>
317	-1994	refer 488	<i>Coil-coated Metal Claddings (R 261)</i>	<i>withdrawn 1/08/2007</i>
318	-1994	refer 595	<i>Care of Coil-Coated Metal Claddings (R 263)</i>	<i>withdrawn 28/1/2016</i>
319	-1994	refer 404	<i>Subfloor Ventilation (R 245)</i>	<i>withdrawn 1/09/2000</i>
320	-1995	refer 495	<i>Stair Design and Safety (R 256)</i>	<i>withdrawn 1/02/2008</i>
321	-1994	refer 620	<i>Reducing the Impact of Wind at Building Sites (R 191)</i>	<i>withdrawn 10/4/2018</i>
322	-1994	nr	<i>Glazing Plastics - (1) Types and Durability (R 241)</i>	<i>withdrawn 30/11/17</i>
323	-1994	nr	<i>Glazing Plastics - (2) Design and Fixing (R 242)</i>	<i>withdrawn 30/11/17</i>
324	-1994	refer 381	<i>Masonry Veneer Cladding - Detailing and Construction (R 94)</i>	<i>withdrawn 1/01/1999</i>
325	-1994	refer 405	<i>Timber Framed Buildings on Exposed Sites (R 207)</i>	<i>withdrawn 1/11/2000</i>
326	-1994	refer 407, 408	<i>Cladding Buildings on Exposed Sites</i>	<i>withdrawn 1/01/2001</i>
327	-1994	nr	<i>Open Fireplaces and Chimneys (R192)</i>	<i>withdrawn 19/6/2017</i>
328	-1994	refer 453	<i>Selection and Use of Fasteners</i>	<i>withdrawn 1/09/2004</i>
329	-1995		<i>Thin Flooring Materials - (1) Selection and Maintenance (R 222)</i>	<i>withdrawn Dec 13 approx</i>
330	-1995		<i>Thin Flooring Materials- (2) Preparation and Laying (R 223)</i>	<i>withdrawn Dec 13 approx</i>
331	-1995	refer 426, 461	<i>Practical Sound Control (R180, 210, 211)</i>	<i>withdrawn 1/06/2005</i>
332	-1995		<i>Claddings in Corrosive Environments</i>	<i>withdrawn nr</i>

BRANZ Bulletin Index
1 August 2021

No.	Issued	New Number	Title	
333	-1995	refer 469	Damp-proof Membranes to Concrete Slabs (R 274)	withdrawn 1/02/2006
334	-1995	refer 427	Reducing Heat Losses From Existing Houses (R201)	withdrawn 1/05/2002
335	-1995	nr	Exposed Aggregate Precast Concrete Panels (R260)	withdrawn 1/01/2015
336	Aug-95	refer 432	Building Papers, Wind Barriers and Vapour Barriers (R277)	withdrawn 1/06/2005
337	Oct-95	refer 636	Protecting Window Glass from Surface Damage (R 236)	withdrawn 1/04/2019
338	Dec-95	refer 434	Rot in Timber	withdrawn 1/04/2003
339	Dec-95	refer tile GPG	Internal Wall Tiling	withdrawn 1/10/1996
340	Feb-96	refer 520	Conservatories (R276)	withdrawn
341	Feb-96	nr	Protecting Valuable Records	withdrawn 1/01/2015
342	Feb-96		External Insulation and Finish Systems (R 287)	withdrawn 1/10/2001
343	Apr-96		Moisture in Timber (R271)	withdrawn
344	Apr-96	refer 491	Embedded Floor Heating (R 293)	withdrawn 1/10/2007
345	Jun-96	no repl	Flat Membrane Roofs - Design and Installation	withdrawn 7/10/2013
346	Jun-96		Flat Membrane Roofs - Materials	withdrawn 1/01/2015
347	Jul-96		Using Kiln-Dried MSG Radiata Pine Framing	withdrawn 1/04/2007
348	Jul-96	refer 458	Domestic Smoke Alarms (R252)	withdrawn 1/02/2005
349	Aug-96	refer 634	Finishes for Aluminium (213, 218)	withdrawn 1/02/2019
350	Oct-96	refer 509	Sizing Gutters and Downpipes (R251)	withdrawn
351	Dec-96	refer 464	Preventing Corrosion of Reinforcing Steel in Concrete (R226)	withdrawn 1/07/2005
352	Dec-96	refer 459	Pole House Construction (R232)	withdrawn 1/04/2005
353	Feb-97	refer 570	Ground Clearances	withdrawn 1/03/2014
354	Feb-97	refer 395	Garage Design	withdrawn 1/01/2000
355	Apr-97	refer 401	Timber Decks	withdrawn 1/07/2000
356	Apr-07	nr	Adhesives for Use with Wood and Wood-based Products (R246)	withdrawn 1/01/2015
357	Jun-97	refer 494, 496	Thermal Insulation of Houses (R292)	withdrawn 1/02/2008
358	Jun-97	New GPG	Crest Fixing of Profiled Metal Roofing (R235)	withdrawn 1/11/2013
359	Aug-97	refer 447	Preventing Moisture Problems in New Buildings (R272)	withdrawn 1/04/2004
360	Aug-97	refer 646	Floor Levelling Compounds (R123)	withdrawn 1/2/2020
361	Oct-97	nr	Weathergrooves (280)	withdrawn 19/6/2017
362	Oct-97	refer 638	Finishes on Architectural Hardware (R249)	withdrawn 1/6/2019
363	Jan-98	refer 535	Repairing Cracks in Concrete (R231)	withdrawn 1/06/2011
364	Jan-98	PDF only	Preventing Noise in Plumbing Installations	
365	Jan-98	refer 505	Acceptable Plans and Specifications	withdrawn 1/11/2008
366	Jan-98	refer 463	Installing Aluminium Windows and Doors	withdrawn 1/07/2005
367	Mar-98	refer 460	Condensation (R278)	withdrawn 1/04/2005
368	Mar-98		Preventing Moisture Problems in Timber Framed Skillion Roofs (R302)	withdrawn 1/06/2007
369	Mar-98		Fitting Tolerances	withdrawn 1/8/20
370	May-98	refer 626	Slip Resistant Floors	withdrawn 27 /07/2018
371	May-98	refer 628	Particleboard Flooring (R294)	withdrawn 28/9/2018
372	Jul-98	refer 592	Durability and Crack Control in Domestic Concrete Floor Construction	withdrawn 1/12/2015
373	Jul-98	refer 451	Specifying Timber (R295)	withdrawn 1/08/2004
374	Sep-98	refer 506	Laying Timber Strip Flooring over Concrete Floor Slabs	withdrawn 1/11/2008
375	Sep-98		Flashings for Aluminium Windows and Doors	withdrawn nr
376	Sep-98		Residential Fire Sprinkler Systems (R262)	withdrawn nr
377	Nov-98		Maintenance of Painted Steelwork (R253)	withdrawn nr
378	Nov-98		Tiling Wet Area Floors	withdrawn nr
379	Nov-98	nr	Preventing Moisture Problems in Existing Buildings (R272)	withdrawn 1/01/2015
380	Jan-99	refer GPG Internal Linings	Timber Internal Linings	withdrawn 19/6/2017
381	Jan-99	refer 436	Masonry Veneer Construction (R324)	withdrawn 1/04/2003
382	Mar-99	refer 623	Curing Concrete (R269)	withdrawn 1/6/18
383	Mar-99	B basics	Reducing Waste from Building Sites	withdrawn 1/11/2013
384	Mar-99		Installing External Doors	withdrawn nr
385	May-99	pdf only	Asphalt Shingles (R289)	
386	May-99	refer 445	Timber Treatment (R275)	withdrawn 1/02/2004
387	May-99	refer 471	Double Glazing	withdrawn 1/04/2006
388	Jul-99	refer 424	Site Measurement of Moisture in Timber and Concrete	withdrawn 1/03/2002

BRANZ Bulletin Index
1 August 2021

No.	Issued	New Number	Title	
389	Jul-99	refer 641	Concrete Toppings	withdrawn 31/7/19
390	Sep-99	refer 645	Laying Timber Strip Flooring Over Timber Joists	withdrawn 19/6/2017
391	Sep-99	refer 532	Site Records	withdrawn
392	Nov-99	refer 487	Swimming Pool Fences	withdrawn 1/08/2007
393	Nov-99	nr	Powder-actuated and Mechanically Powered Fastening Tools (279)	withdrawn 1/01/2015
394	Jan-00	refer 562	Low Retaining Walls	withdrawn 1/08/2013
395	Jan-00	refer 557	Timber Framed Garages (R354)	withdrawn 1/02/2013
396	Jan-00	nr	Wood-Boring Insects	withdrawn 19/6/2017
397	Mar-00		Waterproofing Basements (R290, 291)	withdrawn
398	Mar-00	refer 530	Straw Bale Construction	withdrawn
399	May-00	refer 560	Timber Pile Foundations (R267)	withdrawn 1/05/2013
400	May-00	refer 485	Septic Tanks and Waste Water Systems	withdrawn 1/05/2007
401	Jul-00	refer 462	Constructing Timber Decks (R355)	withdrawn 1/07/2005
402	Jul-00	pdf only	Levels of Finish for Flush-Stopped Linings	withdrawn 1/2/2016
403	Sep-00	nr	Stucco Mixes	withdrawn 1/01/2015
404	Sep-00	refer 457	Ventilation of Enclosed Subfloor Spaces (R319)	withdrawn 1/02/2005
405	Nov-00	refer 563	Timber Framed Buildings on Exposed Sites (R325)	withdrawn 1/08/2013
406	Nov-00	refer 563	Building on the Coast	withdrawn 1/08/2013
407	Jan-01	refer 563	Walls on Exposed Sites (R326)	withdrawn 1/08/2013
408	Jan-01	refer 563	Roofs on Exposed Sites (R326)	withdrawn 1/08/2013
409	Jan-01	refer 580	Contracts in the Building Industry	withdrawn 1/01/2015
410	Jan-01	refer GPG	Selecting Tiles	withdrawn 1/01/2015
411	Apr-01	pdf only	Recommended Timber Cladding Profiles	
412	Mar-01	pdf only	Concrete Driveways	
413	Mar-01	refer GPG Tiling	Substrates for Floor Tiles	withdrawn 19/6/2017
414	May-01	nr	Coping With Climate Change	withdrawn 1/01/2015
415	May-01	refer 466	Timber-Framed Parapets, Balustrades and Columns	withdrawn 1/09/2005
416	May-01	refer 468	Fixing Timber Weatherboards	withdrawn 1/12/2005
417	Jul-01	nr	Maintenance of Concrete Tile Roofs	withdrawn 1/01/2015
418	Jul-01	refer 531	Providing for Thermal and Moisture Movement (R285)	withdrawn 1/02/2011
419	Sep-01	refer 547	Selecting Glass	withdrawn 1/04/2012
420	Sep-01	refer 606	Designing for Fire Safety (R307, 309)	withdrawn 1/2/17
421	Dec-01	refer 566	Windows – Films and Coatings	withdrawn 1/12/2013
422	Feb-02	nr	Maintenance and Refurbishments of Aluminium Joinery (R 286)	withdrawn 1/01/2015
423	Feb-02	refer 559	Pre-Purchase Inspections	withdrawn 1/04/2013
424	Mar-02	refer 515	Measuring Moisture on Building Sites (R388)	withdrawn 1/10/2009
425	Apr-02	nr	Finding Leaks	withdrawn 1/01/2015
426	May-02		Achieving Acoustic Separation (R331 in part)	withdrawn 1/2/2018
427	May-02		Improving Thermal Insulation (R334)	withdrawn
428	Jul-02	nr	Weathertightness Dos and Don'ts	withdrawn 1/01/2015
429	Jul-02	refer House Insulation Guide	Calculating R-Values for Timber Framed Walls	withdrawn 1/05/2015
430	Sep-02	refer 607	Passive Ventilation	withdrawn 1/2/17
431	Sep-02		Care of Kiln Dried Framing Timber	
432	Dec-02	refer 470	Building Papers and Synthetic Wraps (R336)	withdrawn 1/02/2006
433	Feb-03		Weathertightness Checklist	withdrawn 1/11/2013
434	Feb-03	Refer 550	Results of Weathertightness Failure (R338)	withdrawn 1/08/2012
435	Feb-03		Weathertightness Evaluation	withdrawn 1/11/2013
436	Apr-03	refer GPG	Masonry Veneer Construction (R381)	withdrawn 1/07/2007
437	Jun-03	refer GRG	Dealing with Mould (R67)	withdrawn 1/01/2015
438	Aug-03		Using a Scala Penetrometer (R212)	
439	Aug-03		Condensation Risk in Walls (nr)	withdrawn 1/11/2014
440	Oct-03	refer 584	Sealed Joints in External Claddings - (1) Joint Design (R 283)	withdrawn 1/05/2015
441	Oct-03	refer 601	Sealed Joints in External Claddings - (2) Sealants (R 284)	withdrawn 1/8/2016
442	Oct-03	refer 593	Efflorescence on Masonry (R 268)	withdrawn 28/1/2016
443	Dec-03	refer 648	Timber Shingles and Shakes (R288)	withdrawn 30/3/20
444	Dec-03		Lessons from the 1987 Edgcombe Earthquake (R258)	
445	Feb-04	refer 493	Timber Treatment (R386)	withdrawn 1/12/2007

BRANZ Bulletin Index
1 August 2021

No.	Issued	New Number	Title	
446	Feb-04	refer 568	Sustainable Construction	withdrawn 1/02/2014
447	Apr-04	refer 587	Preventing Construction Moisture Problems in New Buildings (R359)	withdrawn 1/07/2015
448	Apr-04	refer 465	Domestic Flashing Installation (R305)	withdrawn 1/09/2005
449	Jun-04	nr	Keeping Water out – Timber Framed Walls (R359)	withdrawn 1/01/2015
450	Jun-04	refer 599	Solar-Control Glass Selection and Installation (R297, 298)	withdrawn 1/6/2016
451	Aug-04	refer 526	Specifying Timber (R373)	withdrawn 1/08/2010
452	Aug-04	Refer 553, 554	Weatherproofing Aluminium Windows	withdrawn 1/11/2012
453	Sep-04	refer 519	Fasteners Selection (R328)	withdrawn 1/02/2010
454	Oct-04	nr	Avoiding Thermal Bridging in Steel-Framed Houses	withdrawn 1/05/2015
455	Oct-04		Restoring a House After Flood Damage (R308)	
456	Nov-04	nr	Alternative Solutions	withdrawn 1/01/2015
457	Feb-05	refer 594	Ventilation of Enclosed Subfloor Spaces (R404)	withdrawn 28/1/2016
458	Feb-05	refer 639	Domestic Fire Protection (R348)	withdrawn 15/8/2018
459	Apr-05	refer 597	Timber Pole House Construction (R352)	withdrawn 31/3/16
460	Apr-05	B basics	Internal Moisture Control (R303, 367)	withdrawn
461	Jun-05		Practical Sound Control (R331)	
462	Jul-05	refer 483	Constructing Timber Decks (R355)	withdrawn 1/04/2007
463	Jul-05	refer 553, 554	Aluminium Windows and E2/AS1 (R366)	withdrawn 1/11/2012
464	Jul-05	refer 574	Prevention of Corrosion in Reinforcing Steel (R351)	withdrawn 1/07/2014
465	Sep-05	refer 567	Domestic Flashing Installation (R305)	withdrawn 1/12/2013
466	Sep-05	refer 561	Timber-Framed Parapets, Balustrades and Columns (R415)	withdrawn 1/05/2013
467	Dec-05	refer 567	Principles of Flashing design (R304)	withdrawn 1/12/2013
468	Dec-05		Fixing Timber weatherboards (R416)	
469	Feb-06	refer 653	Dampproof Membranes to Concrete Slabs (R333)	withdrawn 1/10/2020
470	Feb-06	refer 573	Wall Underlays (432)	withdrawn 7/10/2013
471	Apr-06	refer 598	Insulating Glass Units (R387)	withdrawn 1/6/2016
472	Apr-06	refer 583	Waterproof Decks	withdrawn 1/03/2015
473	Jun-06	refer 600	Heat Pumps	withdrawn 1/8/2016
474	Jun-06		WERS -- Window efficiency rating system	withdrawn 1/11/2014
475	Aug-06	refer 582	Structurally Fixed Cavity Battens	withdrawn 1/03/2015
476	Aug-06	nr	Natural Stone Veneers	withdrawn 21/8/2015
477	Oct-06	refer 524	Solar Water Heating	withdrawn 1/06/2010
478	Oct-06	refer www.level.org.nz and GRG Rainwater Storage Systems	Rainwater Collection for Domestic Use	withdrawn 19/6/2017
479	Dec-06	refer 632	Planning For Maintenance	withdrawn 30/11/18
480	Dec-06	refer 577	Water Heating Systems	withdrawn 1/09/2014
481	Feb-07	refer 658	Timber Windows	withdrawn 1/02/2021
482	Feb-07	refer 539	Downlights	withdrawn 1/10/2011
483	Apr-07	refer 489	Timber Slat Decks (R462)	withdrawn 1/06/2007
484	Apr-07	refer 581	Mechanical Home Ventilation Systems	withdrawn 1/01/2015
485	May-07	refer 637	Domestic On-Site Wastewater Treatment (R400)	withdrawn 1/04/2019
486	May-07	pdf only	BRANZ Household Energy End-use Project	
487	Aug-07	nr	Fencing Swimming Pools, Spas and Hot Tubs (R392)	withdrawn 19/6/2017
488	Aug-07	refer 595	Coil Coated Metal Cladding (R 317)	withdrawn 28/1/2016
489	Aug-07	refer 611	Timber Slat Decks/Balconies (R483)	withdrawn 1/11/2013
490	Oct-07	refer 640	Metal Component Terminology	withdrawn 31/7/19
491	Oct-07	refer 586	Embedded Floor Heating	withdrawn 1/11/2013
492	Dec-07		Slab on Ground Insulation	withdrawn 1/02/2014
493	Dec-07	refer 538	Timber Treatment (445)	withdrawn 1/08/2011
494	Feb-08	refer Building Basics Insulation	Thermal Insulation of New Houses (R357)	withdrawn 19/6/2017
495	Feb-08	refer 625	Stair Design (R320)	withdrawn 27 July 2018

**BRANZ Bulletin Index
1 August 2021**

No.	Issued	New Number	Title	
496	Apr-08	refer Building Basics Insulation and GRG Retrofitting Wall Insulation	Retrofitting Thermal Insulation	withdrawn 19/6/2017
497	Apr-08		Stair Construction	
498	Jun-08		Preparation for Concrete Floor Slabs	
499	Jun-08	refer 621	Site Practices	withdrawn 10/4/2018
500	Aug-08	nr	Optimising Energy Efficient Design of Houses	withdrawn 30/11/17
501	Aug-08	refer Building Basics Insulation	Insulating Suspended Timber Floors	withdrawn 19/6/2017
502	Aug-08	nr	On-site Sequencing	withdrawn 30/11/17
503	Oct-08		Rainwater Harvesting in Commercial and Industrial Buildings	
504	Oct-08	refer 613	NZS 4218 Calculation Method	withdrawn 31/7/17
505	Nov-08	refer 622	Acceptable Plans and Specifications (R365)	withdrawn 10/4/2018
506	Nov-08	refer 644	Laying Solid Timber Strip Flooring on Concrete Slabs (R374)	withdrawn 1/12/2019
507	Feb-08	refer 659	Retrofit Glazing of Timber Windows	withdrawn 1/02/2021
508	Feb-08	refer 581	Heat Recovery Ventilation Systems	withdrawn 1/01/2015
509	Apr-09		Sizing Gutters and Downpipes (R350)	
510	Apr-09		Introduction to Passive Fire Design	withdrawn 20/08/20
511	Jun-09		Residential Roof Drainage Design	
512	Jun-09		Passive Fire Protection – Roles and Responsibilities	withdrawn 20/08/20
513	Aug-09		Timber Composite Overlay Flooring	
514	Aug-09		Passive Fire Protection – On Site Installation	withdrawn 20/08/20
515	Oct-09	refer 585	Measuring Moisture in Timber and Concrete (R424)	withdrawn 1/05/2015
516	Oct-09		Moisture Management in Masonry Veneer	
517	Dec-09		Passive Fire Protection – Maintenance and On-going Compliance	withdrawn 20/08/20
518	Dec-09		Wet Area Tile Waterproofing	
519	Feb-10		Fasteners Selection (R453)	
520	Feb-10		Conservatories (R340)	
521	Apr-10		Squeaky Floors	
522	Apr-10	refer 614	H1 Compliance Options	withdrawn 1/10/2017
523	Jun-10		Reducing Waste from Building Sites (R383)	
524	Jun-10		Solar Water Heating (R477)	
525	Aug-10	refer 610	Preventing Moisture Problems in Timber-framed Skillion Roofs	withdrawn 31/5/2017
526	Aug-10		Specifying Timber (R451)	
527	Oct-10		Drained and Vented Cavities	
528	Oct-10		Metal Tile Roofing	
529	Dec-10		Heat Pump Water Heating	withdrawn 30/9/2015
530	Dec-10		Strawbale Construction (R398)	
531	Feb-11		Designing for Thermal and Moisture Movement (R418)	
532	Feb-11		Site Records (R391)	
533	Apr-11		Green Roofs	
534	Apr-11		Overlay Flooring Systems Over a Suspended Floor	
535	Jun-11		Repairing Cracks in Concrete (R363)	
536	Jun-11		Upgrading Piled Foundations to Resist Earthquakes	
537	Aug-11	refer 556	Internal Gutter Design	withdrawn 1/02/2013
538	Aug-10	refer 575	Timber Treatment (R493)	withdrawn 1/07/2014
539	Oct-11	refer 647	Recessed Downlights (R482)	withdrawn 1/2/2020
540	Oct-11		Solar Gain in Housing (R311)	
541	Dec-11		Concrete Floor Slabs	
542	Dec-12	refer 545	Key Changes to B1/AS1 and E2/AS1	withdrawn 1/02/2012
543	Feb-12		Concrete Finishes	
544	Feb-12		BRANZ Appraisals	withdrawn 1/04/2021
545	Feb-12	refer 652	Key Changes to B1/AS1 and E2/AS1 (R542)	withdrawn 1/08/2020
546	Apr-12		House Condition Survey – External envelope	

BRANZ Bulletin Index
1 August 2021

No.	Issued	New Number	Title	
547	Apr-12		Selecting Glass (R419)	
548	Jun-12		Repairing Plasterboard After an Earthquake	
549	Jun-12		Lintels and Beams Calculator	<i>withdrawn 1/8/2020</i>
550	Aug-12		Damage from Weathertightness Failure (R434)	
551	Aug-12		Learnings from the Canterbury Earthquakes	
552	Oct-12	<i>refer 576</i>	Edge Insulation of Concrete Floor Slabs	<i>withdrawn 1/09/2014</i>
553	Oct-12		Aluminium Joinery Installation in Cavity Construction (R452, 463)	
554	Nov-12		Aluminium Joinery Installation in Direct-fixed Cladding (R452, 463)	
555	Nov-12	<i>refer 629</i>	A Guide to ALF 3.2	<i>withdrawn 28/9/2018</i>
556	Feb-13		Internal Gutter Design (R537)	
557	Feb-13		Timber Framed Garages (R395)	
558	Apr-13		Earthquake Terminology	
559	Apr-13		Pre-Purchase Inspections (R423)	
560	May-13		Pile Foundations (R399)	
561	May-13		Timber-Framed Parapets, Balustrades and Columns (R466)	
562	Aug-13		Low Retaining Walls (R394)	
563	Aug-13		Building on Exposed Sites (R405, 406, 407, 408)	
564	Sep-13		Trombe Walls	
565	Sep-13		Canterbury Earthquakes Royal Commission: Key Recommendations	
566	Dec-13		Applied Window Films (R421)	
567	Dec-13		E2/AS1 Flashing Requirements (R465/467)	
568	Feb-14		Low-impact Homes (R446)	
569	Feb-14		Metal-clad Insulated Panels	
570	Apr-14		Ground Clearances (R353)	
571	Apr-14		Thermal Mass	
572	Jun-14		Aggravated Thermal Bridging Research	
573	Jun-14		Flexible Wall Underlays (R470)	
574	Aug-14		Preventing Corrosion of Reinforcing Steel in Concrete (R464)	
575	Aug-14		Timber Treatment (R538)	
576	Oct-14		Edge Insulation of Concrete Floor Slabs (R552)	
577	Oct-14		Water Heating Systems (R480)	
578	Dec-14		Ventilation Drying Behind Wall Claddings	
579	Dec-14		Windows Energy Efficiency Rating System (WEERS) (R474)	
580	Feb-15	<i>refer 590</i>	Contracts in the Building Industry (R409)	<i>withdrawn 30/9/2015</i>
581	Feb-15		Residential Mechanical Ventilation Systems (R484 and 508)	
582	Apr-15		Structurally Fixed Cavity Battens (R475)	
583	Apr-15		Waterproof Decks (R472)	
584	Jun-15		Sealed Joint Design – Claddings (R440)	
585	Jun-15		Measuring Moisture in Timber and Concrete (R515)	
586	Aug-15		Embedded Floor Heating (R491)	
587	Aug-15		Dealing with Construction Moisture in New Buildings (R447)	
588	Oct-15		BRANZ Maps and Wind Zone Calculations	
589	Oct-15		Heat Pump Water Heating (R529)	
590	Oct-15		Contracts in the Building Industry (R580)	
591	Dec-15		Waterproofing Tiled Showers	
592	Dec-15		Concrete Slab-on-Ground Floors (R372)	
593	Feb-16		Efflorescence (R442)	
594	Feb-16		Excessive Moisture in Enclosed Subfloor Spaces (R457)	
595	Feb-16		Factory-coated Metal Claddings (R318 and 488)	
596	Apr-16		An Introduction to Life Cycle Assessment	
597	Apr-16		Timber Pole House Construction (R459)	
598	Jun-16		Insulating Glass Units (IGUs) (R471)	
599	Jun-16		Solar-control Glazing (R450)	
600	Aug-16		Heat Pumps (R473)	

BRANZ Bulletin Index
1 August 2021

No.	Issued	New Number	Title
601	Aug-16		Sealants for Cladding Joints (R441)
602	Oct-16		Thermal Modelling Tools for Houses
603	Oct-16		Environmental Product Declarations
604	Dec-16		Vapour Control in New Zealand buildings
605	Dec-16		Residential Glazing Safety (R313)
606	Feb-17		Residential Fire Safety (R420)
607	Feb-17		Passive Ventilation (R430)
608	Apr-17		Building Life Cycle Assessment
609	Apr-17		Photovoltaic Systems for Dwellings
610	Jun-17		Preventing Moisture Problems in Timber-framed Skillion Roofs (R525)
611	Jun-17		Timber Slat Decks (R489)
612	Aug-17		Load Paths
613	Aug-17		NZS 4218:2009 Calculation Method (R504)
614	Oct-17		H1 Compliance Options (R522)
615	Oct-17		Critical Connections
616	Dec-17		Wall Bracing in NZS 3604:2011 Buildings
617	Dec-17		Subfloor and Roof Bracing in NZS 3604:2011 Buildings
618	Feb-18		Acoustic Design Principles (R426)
619	Feb-18		House Condition Survey 2015
620	Apr-18		Managing Wind Effects Around Buildings (R321)
621	Apr-18		Site Practices (R499)
622	Apr-18		Good Plans and Specifications (R505)
623	Jun-18		Curing Concrete (R382)
624	Jun-18		An Introduction to WUFI
625	Aug-18		Stair Design (R495)
626	Aug-18		Slip Resistance of Floors (R370)
627	Aug-18		The Impact of Geothermal Environments on Metals and Wood
628	Oct-18		Sheet Flooring (R371)
629	Oct-18		ALF 4.0 Building Performance Index Calculator (R555)
630	Dec-18		Roof Space Ventilation
631	Dec-18		How Micro-environments Affect Material Performance
632	Dec-18		Planning for Maintenance (R479)
633	Feb-19		Removing Paint Coatings (R314)
634	Feb-19		Finishing Aluminium (R349)
635	Feb-19		Bracing Distribution
636	Apr-19		Protecting Glass from Damage (R337)
637	Apr-19		Domestic On-Site Foulwater Treatment (R485)
638	Jun-19		Finishes on Architectural Hardware (R362)
639	Jun-19		Domestic Active Fire Protection (R458)
640	Aug-19		Metal Component Terminology (R490)
641	Aug-19		Concrete Toppings (R389)
642	Dec-19		Changes in the Condition of New Zealand Houses over 25 Years
643	Dec-19		Energy Efficiency in New Zealand Houses
644	Dec-19		Solid Timber Strip Flooring on a Concrete Slab (R506)
645	Dec-19		Installing Timber Strip Flooring over Timber Joists (R390)
646	Feb-20		Floor Levelling Compounds (R360)
647	Feb-20		Recessed Luminaires (R539)
648	Apr-20		Timber Shingle and Shake Roofing (R443)
649	Apr-20		Corrosion of Metals in New Zealand Buildings
650	Jun-20		Building Beyond Code Minimums
651	Jun-20		Climate Change, Net-Zero Carbon and the Building Industry
652	Aug-20		Amendments to Acceptable Solutions and Verification Methods for B1 and E2 (R545)
653	Oct-20		Damp-proof Membranes to Concrete Slabs (R469)
654	Oct-20		Installation and Maintenance of Solid Fuel Appliances (R306)
655	Oct-20		Building Blocks for New-build Net-zero Carbon Houses

BRANZ Bulletin Index
1 August 2021

No.	Issued	New Number	Title	
656	Dec-20		Designing to Avoid Houses Overheating	
657	Dec-20		Designing Water-efficient Houses	
658	Feb-21		Timber Windows (R481)	
659	Feb-21		Upgrading the Thermal Performance of Timber Windows (R507)	
660	Apr-21		Residential Walls with High Thermal Performance	
661	Apr-21		Residential Roofs with High Thermal Performance	
662	Jun-21		Universal design for access into homes	
663	Jun-21		Universal design for access into homes by vehicle	
664	Aug-21		Residential rainwater systems	
665	Aug-21		Residential greywater systems	