

BRANZ Bulletin Index
11 Sep 2023

Titles in **Bold** are current Bulletins

Titles in *Italics* indicate Bulletins that have been withdrawn

Bulletins are available as a downloadable PDFs from the BRANZ shop. Withdrawn bulletins are available from the BRANZ library service.

nr = bulletin withdrawn, no replacement

(RXXX) refers to the bulletin the title replaced

No.	Issued	New Number	Title	
686	Sep-23		Building with 140 mm timber exterior wall framing	
685	Jul-23		Insulation of concrete slab-on-ground floors less than 300 m2	
684	May-23		Thermal modelling tools for houses	
683	May-23		The rules for sleepouts that don't need a building consent	
682	Mar-23		Specifying glazing	
681	Mar-23		Introduction to engineered wood products (EWPs)	
680	Dec-22		Insulating glass units (IGUs) (R598)	
679	Dec-22		Introduction to calculating whole-of-life carbon footprint of houses	
678	Dec-22		H1 Calculation method - housing, and buildings up to 300 m2 (R613)	
677	Oct-22		Specifying roofs under H1	
676	Oct-22		Complying with H1-Housing, and buildings up to 300 m2 (R668)	
675	Aug-22		Using a scala penetrometer (R438)	
674	Aug-22		Seismic retrofitting houses with piled foundations on sloping sites	
673	Jun-22		Cavity battens (582)	
672	Jun-22		Specifying floors under H1	<i>Minor updates Oct-22</i>
671	Apr-22		Reducing construction and demolition waste (R523)	
670	Apr-22		Specifying windows and doors under H1	<i>Minor updates Oct-22</i>
669	Feb-22		Tools for measuring carbon in new-build houses	
<i>668</i>	<i>Feb-22</i>	<i>refer 676</i>	<i>Complying with H1-Housing, and buildings up to 300 m2</i>	<i>Withdrawn Oct-22</i>
667	Dec-21		Earth buildings	
666	Dec-21		Restoring a home after flood damage (R455)	
665	Aug-21		Residential greywater systems	
664	Aug-21		Residential rainwater systems	
663	Jun-21		Universal design for access into homes by vehicle	
662	Jun-21		Universal design for access into homes	
<i>661</i>	<i>Apr-21</i>		<i>Residential Roofs with High Thermal Performance</i>	<i>Withdrawn Oct-22</i>
<i>660</i>	<i>Apr-21</i>		<i>Residential Walls with High Thermal Performance</i>	<i>Withdrawn Oct-22</i>
659	Feb-21		Upgrading the Thermal Performance of Timber Windows (R507)	
658	Feb-21		Timber Windows (R481)	
657	Dec-20		Designing Water-efficient Houses	
<i>656</i>	<i>Dec-20</i>		<i>Designing to Avoid Houses Overheating</i>	<i>Withdrawn Oct-22</i>
<i>655</i>	<i>Oct-20</i>		<i>Building Blocks for New-build Net-zero Carbon Houses</i>	<i>Withdrawn Oct-22</i>
654	Oct-20		Installation and Maintenance of Solid Fuel Appliances (R306)	
<i>653</i>	<i>Oct-20</i>		<i>Damp-proof Membranes to Concrete Slabs (R469)</i>	<i>Withdrawn Oct-22</i>
652	Aug-20		Amendments to Acceptable Solutions and Verification Methods for B1 and E2 (R545)	
651	Jun-20		Climate Change, Net-Zero Carbon and the Building Industry	
<i>650</i>	<i>Jun-20</i>	<i>nr</i>	<i>Building Beyond Code Minimums</i>	<i>Withdrawn Oct-22</i>
649	Apr-20		Corrosion of Metals in New Zealand Buildings	
648	Apr-20		Timber Shingle and Shake Roofing (R443)	
647	Feb-20		Recessed Luminaires (R539)	
646	Feb-20		Floor Levelling Compounds (R360)	
645	Dec-19		Installing Timber Strip Flooring over Timber Joists (R390)	
644	Dec-19		Solid Timber Strip Flooring on a Concrete Slab (R506)	
643	Dec-19		Energy Efficiency in New Zealand Houses	
642	Dec-19		Changes in the Condition of New Zealand Houses over 25 Years	
641	Aug-19		Concrete Toppings (R389)	
640	Aug-19		Metal Component Terminology (R490)	

BRANZ Bulletin Index
11 Sep 2023

639	Jun-19		Domestic Active Fire Protection (R458)	
638	Jun-19		Finishes on Architectural Hardware (R362)	
637	Apr-19		Domestic On-Site Foulwater Treatment (R485)	
636	Apr-19		Protecting Glass from Damage (R337)	Minor update Dec-22
635	Feb-19		Bracing Distribution	
634	Feb-19		Finishing Aluminium (R349)	
633	Feb-19		Removing Paint Coatings (R314)	
632	Dec-18		Planning for Maintenance (R479)	Minor update Dec-22
631	Dec-18		How Micro-environments Affect Material Performance	
630	Dec-18		Roof Space Ventilation	
629	Oct-18	nr	ALF 4.0 Building Performance Index Calculator (R555)	Withdrawn Oct-22
628	Oct-18		Sheet Flooring (R371)	
627	Aug-18		The Impact of Geothermal Environments on Metals and Wood	
626	Aug-18		Slip Resistance of Floors (R370)	
625	Aug-18		Stair Design (R495)	
624	Jun-18		An Introduction to WUFI	
623	Jun-18		Curing Concrete (R382)	
622	Apr-18		Good Plans and Specifications (R505)	
621	Apr-18		Site Practices (R499)	
620	Apr-18		Managing Wind Effects Around Buildings (R321)	
619	Feb-18		House Condition Survey 2015	
618	Feb-18		Acoustic Design Principles (R426)	
617	Dec-17		Subfloor and Roof Bracing in NZS 3604:2011 Buildings	
616	Dec-17		Wall Bracing in NZS 3604:2011 Buildings	
615	Oct-17		Critical Connections	
614	Oct-17	nr	H1 Compliance Options (R522)	Withdrawn Oct-22
613	Aug-17	refer 678	NZS 4218:2009 Calculation Method (R504)	Withdrawn Oct-22
612	Aug-17		Load Paths	
611	Jun-17		Timber Slat Decks (R489)	
610	Jun-17		Preventing Moisture Problems in Timber-framed Skillion Roofs (R525)	
609	Apr-17		Photovoltaic Systems for Dwellings	
608	Apr-17		Building Life Cycle Assessment	
607	Feb-17		Passive Ventilation (R430)	
606	Feb-17		Residential Fire Safety (R420)	
605	Dec-16		Residential Glazing Safety (R313)	Withdrawn Oct-22
604	Dec-16		Vapour Control in New Zealand buildings	
603	Oct-16		Environmental Product Declarations	Minor update Mar-23
602	Oct-16		Thermal Modelling Tools for Houses	Withdrawn Oct-22
601	Aug-16		Sealants for Cladding Joints (R441)	
600	Aug-16		Heat Pumps (R473)	
599	Jun-16		Solar-control Glazing (R450)	Withdrawn Oct-22
598	Jun-16	refer 680	Insulating Glass Units (IGUs) (R471)	Withdrawn Oct-22
597	Apr-16		Timber Pole House Construction (R459)	
596	Apr-16		An Introduction to Life Cycle Assessment	
595	Feb-16		Factory-coated Metal Claddings (R318 and 488)	
594	Feb-16		Excessive Moisture in Enclosed Subfloor Spaces (R457)	
593	Feb-16		Efflorescence (R442)	
592	Dec-15		Concrete Slab-on-Ground Floors (R372)	Withdrawn Oct-22
591	Dec-15		Waterproofing Tiled Showers	
590	Oct-15		Contracts in the Building Industry (R580)	
589	Oct-15		Heat Pump Water Heating (R529)	
588	Oct-15		BRANZ Maps and Wind Zone Calculations	Minor update Mar-23
587	Aug-15		Dealing with Construction Moisture in New Buildings (R447)	
586	Aug-15		Embedded Floor Heating (R491)	
585	Jun-15		Measuring Moisture in Timber and Concrete (R515)	
584	Jun-15		Sealed Joint Design – Claddings (R440)	
583	Apr-15		Waterproof Decks (R472)	
582	Apr-15	refer 673	Structurally Fixed Cavity Battens (R475)	Withdrawn Jun-2022
581	Feb-15		Residential Mechanical Ventilation Systems (R484 and 508)	
580	Feb-15	refer 590	Contracts in the Building Industry (R409)	Withdrawn 30/9/2015

BRANZ Bulletin Index
11 Sep 2023

579	Dec-14	nr	Windows Energy Efficiency Rating System (WEERS) (R474)	Withdrawn Oct-22
578	Dec-14		Ventilation Drying Behind Wall Claddings	
577	Oct-14		Water Heating Systems (R480)	
576	Oct-14		Edge Insulation of Concrete Floor Slabs (R552)	Withdrawn Oct-22
575	Aug-14		Timber Treatment (R538)	
574	Aug-14		Preventing Corrosion of Reinforcing Steel in Concrete (R464)	
573	Jun-14		Flexible Wall Underlays (R470)	
572	Jun-14		Aggravated Thermal Bridging Research	
571	Apr-14		Thermal Mass	
570	Apr-14		Ground Clearances (R353)	
569	Feb-14		Metal-clad Insulated Panels	
568	Feb-14		Low-impact Homes (R446)	
567	Dec-13		E2/AS1 Flashing Requirements (R465/467)	
566	Dec-13		Applied Window Films (R421)	
565	Sep-13		Canterbury Earthquakes Royal Commission: Key Recommendations	
564	Sep-13		Trombe Walls	
563	Aug-13		Building on Exposed Sites (R405, 406, 407, 408)	
562	Aug-13		Low Retaining Walls (R394)	
561	May-13		Timber-Framed Parapets, Balustrades and Columns (R466)	
560	May-13		Pile Foundations (R399)	
559	Apr-13		Pre-Purchase Inspections (R423)	
558	Apr-13		Earthquake Terminology	
557	Feb-13		Timber Framed Garages (R395)	
556	Feb-13		Internal Gutter Design (R537)	
555	Nov-12	refer 629	A Guide to ALF 3.2	withdrawn 28/9/2018
554	Nov-12		Aluminium Joinery Installation in Direct-fixed Cladding (R452, 463)	Withdrawn Oct. 2022
553	Oct-12		Aluminium Joinery Installation in Cavity Construction (R452, 463)	Withdrawn Oct. 2022
552	Oct-12	refer 576	Edge Insulation of Concrete Floor Slabs	withdrawn 1/09/2014
551	Aug-12		Learnings from the Canterbury Earthquakes	
550	Aug-12		Damage from Weathertightness Failure (R434)	
549	Jun-12		Lintels and Beams Calculator	withdrawn 1/8/2020
548	Jun-12		Repairing Plasterboard After an Earthquake	
547	Apr-12		Selecting Glass (R419)	Withdrawn Oct-22
546	Apr-12		House Condition Survey – External envelope	
545	Feb-12	refer 652	Key Changes to B1/AS1 and E2/AS1 (R542)	withdrawn 1/08/2020
544	Feb-12		BRANZ Appraisals	withdrawn 1/04/2021
543	Feb-12		Concrete Finishes	
542	Dec-12	refer 545	Key Changes to B1/AS1 and E2/AS1	withdrawn 1/02/2012
541	Dec-11		Concrete Floor Slabs	
540	Oct-11		Solar Gain in Housing (R311)	Withdrawn Oct-22
539	Oct-11	refer 647	Recessed Downlights (R482)	withdrawn 1/2/2020
538	Aug-10	refer 575	Timber Treatment (R493)	withdrawn 1/07/2014
537	Aug-11	refer 556	Internal Gutter Design	withdrawn 1/02/2013
536	Jun-11		Upgrading Piled Foundations to Resist Earthquakes	
535	Jun-11		Repairing Cracks in Concrete (R363)	
534	Apr-11		Overlay Flooring Systems Over a Suspended Floor	
533	Apr-11		Green Roofs	
532	Feb-11		Site Records (R391)	
531	Feb-11		Designing for Thermal and Moisture Movement (R418)	
530	Dec-10		Strawbale Construction (R398)	
529	Dec-10		Heat Pump Water Heating	withdrawn 30/9/2015
528	Oct-10		Metal Tile Roofing	
527	Oct-10		Drained and Vented Cavities	
526	Aug-10		Specifying Timber (R451)	
525	Aug-10	refer 610	Preventing Moisture Problems in Timber-framed Skillion Roofs	withdrawn 31/5/2017
524	Jun-10		Solar Water Heating (R477)	
523	Jun-10	refer 671	Reducing Waste from Building Sites (R383)	withdrawn 1/04/2022
522	Apr-10	refer 614	H1 Compliance Options	withdrawn 1/10/2017
521	Apr-10		Squeaky Floors	

BRANZ Bulletin Index
11 Sep 2023

520	Feb-10		Conservatories (R340)	
519	Feb-10		Fasteners Selection (R453)	
518	Dec-09		Wet Area Tile Waterproofing	
517	Dec-09		Passive Fire Protection – Maintenance and On-going Compliance	withdrawn 20/08/20
516	Oct-09		Moisture Management in Masonry Veneer	
515	Oct-09	refer 585	Measuring Moisture in Timber and Concrete (R424)	withdrawn 1/05/2015
514	Aug-09		Passive Fire Protection – On Site Installation	withdrawn 20/08/20
513	Aug-09		Timber Composite Overlay Flooring	
512	Jun-09		Passive Fire Protection – Roles and Responsibilities	withdrawn 20/08/20
511	Jun-09		Residential Roof Drainage Design	
510	Apr-09		Introduction to Passive Fire Design	withdrawn 20/08/20
509	Apr-09		Sizing Gutters and Downpipes (R350)	
508	Feb-08	refer 581	Heat Recovery Ventilation Systems	withdrawn 1/01/2015
507	Feb-08	refer 659	Retrofit Glazing of Timber Windows	withdrawn 1/02/2021
506	Nov-08	refer 644	Laying Solid Timber Strip Flooring on Concrete Slabs (R374)	withdrawn 1/12/2019
505	Nov-08	refer 622	Acceptable Plans and Specifications (R365)	withdrawn 10/4/2018
504	Oct-08	refer 613	NZS 4218 Calculation Method	withdrawn 31/7/17
503	Oct-08		Rainwater Harvesting in Commercial and Industrial Buildings	
502	Aug-08	nr	On-site Sequencing	withdrawn 30/11/17
501	Aug-08	refer Building Basics Insulation	Insulating Suspended Timber Floors	withdrawn 19/6/2017
500	Aug-08	nr	Optimising Energy Efficient Design of Houses	withdrawn 30/11/17
499	Jun-08	refer 621	Site Practices	withdrawn 10/4/2018
498	Jun-08		Preparation for Concrete Floor Slabs	
497	Apr-08		Stair Construction	
496	Apr-08	refer Building Basics Insulation and GRG Retrofitting Wall Insulation	Retrofitting Thermal Insulation	withdrawn 19/6/2017
495	Feb-08	refer 625	Stair Design (R320)	withdrawn 27 July 2018
494	Feb-08	refer Building Basics Insulation	Thermal Insulation of New Houses (R357)	withdrawn 19/6/2017
493	Dec-07	refer 538	Timber Treatment (445)	withdrawn 1/08/2011
492	Dec-07		Slab on Ground Insulation	withdrawn 1/02/2014
491	Oct-07	refer 586	Embedded Floor Heating	withdrawn 1/11/2013
490	Oct-07	refer 640	Metal Component Terminology	withdrawn 31/7/19
489	Aug-07	refer 611	Timber Slat Decks/Balconies (R483)	withdrawn 1/11/2013
488	Aug-07	refer 595	Coil Coated Metal Cladding (R 317)	withdrawn 28/1/2016
487	Aug-07	nr	Fencing Swimming Pools, Spas and Hot Tubs (R392)	withdrawn 19/6/2017
486	May-07	pdf only	BRANZ Household Energy End-use Project	
485	May-07	refer 637	Domestic On-Site Wastewater Treatment (R400)	withdrawn 1/04/2019
484	Apr-07	refer 581	Mechanical Home Ventilation Systems	withdrawn 1/01/2015
483	Apr-07	refer 489	Timber Slat Decks (R462)	withdrawn 1/06/2007
482	Feb-07	refer 539	Downlights	withdrawn 1/10/2011
481	Feb-07	refer 658	Timber Windows	withdrawn 1/02/2021
480	Dec-06	refer 577	Water Heating Systems	withdrawn 1/09/2014
479	Dec-06	refer 632	Planning For Maintenance	withdrawn 30/11/18
478	Oct-06	refer www.level.org.nz and GRG Rainwater Storage Systems	Rainwater Collection for Domestic Use	withdrawn 19/6/2017
477	Oct-06	refer 524	Solar Water Heating	withdrawn 1/06/2010
476	Aug-06	nr	Natural Stone Veneers	withdrawn 21/8/2015
475	Aug-06	refer 582	Structurally Fixed Cavity Battens	withdrawn 1/03/2015
474	Jun-06		WERS -- Window efficiency rating system	withdrawn 1/11/2014
473	Jun-06	refer 600	Heat Pumps	withdrawn 1/8/2016
472	Apr-06	refer 583	Waterproof Decks	withdrawn 1/03/2015
471	Apr-06	refer 598	Insulating Glass Units (R387)	withdrawn 1/6/2016
470	Feb-06	refer 573	Wall Underlays (432)	withdrawn 7/10/2013

BRANZ Bulletin Index
11 Sep 2023

469	Feb-06	refer 653	Dampproof Membranes to Concrete Slabs (R333)	withdrawn 1/10/2020
468	Dec-05		Fixing Timber weatherboards (R416)	
467	Dec-05	refer 567	Principles of Flashing design (R304)	withdrawn 1/12/2013
466	Sep-05	refer 561	Timber-Framed Parapets, Balustrades and Columns (R415)	withdrawn 1/05/2013
465	Sep-05	refer 567	Domestic Flashing Installation (R305)	withdrawn 1/12/2013
464	Jul-05	refer 574	Prevention of Corrosion in Reinforcing Steel (R351)	withdrawn 1/07/2014
463	Jul-05	refer 553, 554	Aluminium Windows and E2/AS1 (R366)	withdrawn 1/11/2012
462	Jul-05	refer 483	Constructing Timber Decks (R355)	withdrawn 1/04/2007
461	Jun-05		Practical Sound Control (R331)	
460	Apr-05	B basics	Internal Moisture Control (R303, 367)	withdrawn
459	Apr-05	refer 597	Timber Pole House Construction (R352)	withdrawn 31/3/16
458	Feb-05	refer 639	Domestic Fire Protection (R348)	withdrawn 15/8/2018
457	Feb-05	refer 594	Ventilation of Enclosed Subfloor Spaces (R404)	withdrawn 28/1/2016
456	Nov-04	nr	Alternative Solutions	withdrawn 1/01/2015
455	Oct-04	refer 666	Restoring a House After Flood Damage (R308)	withdrawn 1/12/2021
454	Oct-04	nr	Avoiding Thermal Bridging in Steel-Framed Houses	withdrawn 1/05/2015
453	Sep-04	refer 519	Fasteners Selection (R328)	withdrawn 1/02/2010
452	Aug-04	Refer 553, 554	Weatherproofing Aluminium Windows	withdrawn 1/11/2012
451	Aug-04	refer 526	Specifying Timber (R373)	withdrawn 1/08/2010
450	Jun-04	refer 599	Solar-Control Glass Selection and Installation (R297, 298)	withdrawn 1/6/2016
449	Jun-04	nr	Keeping Water out – Timber Framed Walls (R359)	withdrawn 1/01/2015
448	Apr-04	refer 465	Domestic Flashing Installation (R305)	withdrawn 1/09/2005
447	Apr-04	refer 587	Preventing Construction Moisture Problems in New Buildings (R359)	withdrawn 1/07/2015
446	Feb-04	refer 568	Sustainable Construction	withdrawn 1/02/2014
445	Feb-04	refer 493	Timber Treatment (R386)	withdrawn 1/12/2007
444	Dec-03		Lessons from the 1987 Edgecumbe Earthquake (R258)	
443	Dec-03	refer 648	Timber Shingles and Shakes (R288)	withdrawn 30/3/20
442	Oct-03	refer 593	Efflorescence on Masonry (R 268)	withdrawn 28/1/2016
441	Oct-03	refer 601	Sealed Joints in External Claddings - (2) Sealants (R 284)	withdrawn 1/8/2016
440	Oct-03	refer 584	Sealed Joints in External Claddings - (1) Joint Design (R 283)	withdrawn 1/05/2015
439	Aug-03		Condensation Risk in Walls (nr)	withdrawn 1/11/2014
438	Aug-03	refer 675	Using a Scala Penetrometer (R212)	Withdrawn August 2022
437	Jun-03	refer GRG	Dealing with Mould (R67)	withdrawn 1/01/2015
436	Apr-03	refer GPG	Masonry Veneer Construction (R381)	withdrawn 1/07/2007
435	Feb-03		Weathertightness Evaluation	withdrawn 1/11/2013
434	Feb-03	Refer 550	Results of Weathertightness Failure (R338)	withdrawn 1/08/2012
433	Feb-03		Weathertightness Checklist	withdrawn 1/11/2013
432	Dec-02	refer 470	Building Papers and Synthetic Wraps (R336)	withdrawn 1/02/2006
431	Sep-02		Care of Kiln Dried Framing Timber	
430	Sep-02	refer 607	Passive Ventilation	withdrawn 1/2/17
429	Jul-02	refer House Insulation Guide	Calculating R-Values for Timber Framed Walls	withdrawn 1/05/2015
428	Jul-02	nr	Weathertightness Dos and Don'ts	withdrawn 1/01/2015
427	May-02		Improving Thermal Insulation (R334)	withdrawn
426	May-02		Achieving Acoustic Separation (R331 in part)	withdrawn 1/2/2018
425	Apr-02	nr	Finding Leaks	withdrawn 1/01/2015
424	Mar-02	refer 515	Measuring Moisture on Building Sites (R388)	withdrawn 1/10/2009
423	Feb-02	refer 559	Pre-Purchase Inspections	withdrawn 1/04/2013
422	Feb-02	nr	Maintenance and Refurbishments of Aluminium Joinery (R 286)	withdrawn 1/01/2015
421	Dec-01	refer 566	Windows – Films and Coatings	withdrawn 1/12/2013
420	Sep-01	refer 606	Designing for Fire Safety (R307, 309)	withdrawn 1/2/17
419	Sep-01	refer 547	Selecting Glass	withdrawn 1/04/2012
418	Jul-01	refer 531	Providing for Thermal and Moisture Movement (R285)	withdrawn 1/02/2011
417	Jul-01	nr	Maintenance of Concrete Tile Roofs	withdrawn 1/01/2015
416	May-01	refer 468	Fixing Timber Weatherboards	withdrawn 1/12/2005
415	May-01	refer 466	Timber-Framed Parapets, Balustrades and Columns	withdrawn 1/09/2005
414	May-01	nr	Coping With Climate Change	withdrawn 1/01/2015
413	Mar-01	refer GPG Tiling	Substrates for Floor Tiles	withdrawn 19/6/2017
412	Mar-01	pdf only	Concrete Driveways	
411	Apr-01	pdf only	Recommended Timber Cladding Profiles	

BRANZ Bulletin Index
11 Sep 2023

410	Jan-01	refer GPG	Selecting Tiles	withdrawn 1/01/2015
409	Jan-01	refer 580	Contracts in the Building Industry	withdrawn 1/01/2015
408	Jan-01	refer 563	Roofs on Exposed Sites (R326)	withdrawn 1/08/2013
407	Jan-01	refer 563	Walls on Exposed Sites (R326)	withdrawn 1/08/2013
406	Nov-00	refer 563	Building on the Coast	withdrawn 1/08/2013
405	Nov-00	refer 563	Timber Framed Buildings on Exposed Sites (R325)	withdrawn 1/08/2013
404	Sep-00	refer 457	Ventilation of Enclosed Subfloor Spaces (R319)	withdrawn 1/02/2005
403	Sep-00	nr	Stucco Mixes	withdrawn 1/01/2015
402	Jul-00	pdf only	Levels of Finish for Flush-Stopped Linings	withdrawn 1/2/2016
401	Jul-00	refer 462	Constructing Timber Decks (R355)	withdrawn 1/07/2005
400	May-00	refer 485	Septic Tanks and Waste Water Systems	withdrawn 1/05/2007
399	May-00	refer 560	Timber Pile Foundations (R267)	withdrawn 1/05/2013
398	Mar-00	refer 530	Straw Bale Construction	withdrawn
397	Mar-00		Waterproofing Basements (R290, 291)	withdrawn
396	Jan-00	nr	Wood-Boring Insects	withdrawn 19/6/2017
395	Jan-00	refer 557	Timber Framed Garages (R354)	withdrawn 1/02/2013
394	Jan-00	refer 562	Low Retaining Walls	withdrawn 1/08/2013
393	Nov-99	nr	Powder-actuated and Mechanically Powered Fastening Tools (279)	withdrawn 1/01/2015
392	Nov-99	refer 487	Swimming Pool Fences	withdrawn 1/08/2007
391	Sep-99	refer 532	Site Records	withdrawn
390	Sep-99	refer 645	Laying Timber Strip Flooring Over Timber Joists	withdrawn 19/6/2017
389	Jul-99	refer 641	Concrete Toppings	withdrawn 31/7/19
388	Jul-99	refer 424	Site Measurement of Moisture in Timber and Concrete	withdrawn 1/03/2002
387	May-99	refer 471	Double Glazing	withdrawn 1/04/2006
386	May-99	refer 445	Timber Treatment (R275)	withdrawn 1/02/2004
385	May-99	pdf only	Asphalt Shingles (R289)	
384	Mar-99		Installing External Doors	withdrawn nr
383	Mar-99	B basics	Reducing Waste from Building Sites	withdrawn 1/11/2013
382	Mar-99	refer 623	Curing Concrete (R269)	withdrawn 1/6/18
381	Jan-99	refer 436	Masonry Veneer Construction (R324)	withdrawn 1/04/2003
380	Jan-99	refer GPG Internal Linings	Timber Internal Linings	withdrawn 19/6/2017
379	Nov-98	nr	Preventing Moisture Problems in Existing Buildings (R272)	withdrawn 1/01/2015
378	Nov-98		Tiling Wet Area Floors	withdrawn nr
377	Nov-98		Maintenance of Painted Steelwork (R253)	withdrawn nr
376	Sep-98		Residential Fire Sprinkler Systems (R262)	withdrawn nr
375	Sep-98		Flashings for Aluminium Windows and Doors	withdrawn nr
374	Sep-98	refer 506	Laying Timber Strip Flooring over Concrete Floor Slabs	withdrawn 1/11/2008
373	Jul-98	refer 451	Specifying Timber (R295)	withdrawn 1/08/2004
372	Jul-98	refer 592	Durability and Crack Control in Domestic Concrete Floor Construction	withdrawn 1/12/2015
371	May-98	refer 628	Particleboard Flooring (R294)	withdrawn 28/9/2018
370	May-98	refer 626	Slip Resistant Floors	withdrawn 27/07/2018
369	Mar-98		Fitting Tolerances	withdrawn 1/8/20
368	Mar-98		Preventing Moisture Problems in Timber Framed Skillion Roofs (R302)	withdrawn 1/06/2007
367	Mar-98	refer 460	Condensation (R278)	withdrawn 1/04/2005
366	Jan-98	refer 463	Installing Aluminium Windows and Doors	withdrawn 1/07/2005
365	Jan-98	refer 505	Acceptable Plans and Specifications	withdrawn 1/11/2008
364	Jan-98	PDF only	Preventing Noise in Plumbing Installations	
363	Jan-98	refer 535	Repairing Cracks in Concrete (R231)	withdrawn 1/06/2011
362	Oct-97	refer 638	Finishes on Architectural Hardware (R249)	withdrawn 1/6/2019
361	Oct-97	nr	Weathergrooves (280)	withdrawn 19/6/2017
360	Aug-97	refer 646	Floor Levelling Compounds (R123)	withdrawn 1/2/2020
359	Aug-97	refer 447	Preventing Moisture Problems in New Buildings (R272)	withdrawn 1/04/2004
358	Jun-97	New GPG	Crest Fixing of Profiled Metal Roofing (R235)	withdrawn 1/11/2013
357	Jun-97	refer 494, 496	Thermal Insulation of Houses (R292)	withdrawn 1/02/2008
356	Apr-07	nr	Adhesives for Use with Wood and Wood-based Products (R246)	withdrawn 1/01/2015
355	Apr-97	refer 401	Timber Decks	withdrawn 1/07/2000
354	Feb-97	refer 395	Garage Design	withdrawn 1/01/2000

BRANZ Bulletin Index
11 Sep 2023

353	Feb-97	refer 570	Ground Clearances	withdrawn 1/03/2014
352	Dec-96	refer 459	Pole House Construction (R232)	withdrawn 1/04/2005
351	Dec-96	refer 464	Preventing Corrosion of Reinforcing Steel in Concrete (R226)	withdrawn 1/07/2005
350	Oct-96	refer 509	Sizing Gutters and Downpipes (R251)	withdrawn
349	Aug-96	refer 634	Finishes for Aluminium (213, 218)	withdrawn 1/02/2019
348	Jul-96	refer 458	Domestic Smoke Alarms (R252)	withdrawn 1/02/2005
347	Jul-96		Using Kiln-Dried MSG Radiata Pine Framing	withdrawn 1/04/2007
346	Jun-96		Flat Membrane Roofs - Materials	withdrawn 1/01/2015
345	Jun-96	no repl	Flat Membrane Roofs - Design and Installation	withdrawn 7/10/2013
344	Apr-96	refer 491	Embedded Floor Heating (R 293)	withdrawn 1/10/2007
343	Apr-96		Moisture in Timber (R271)	withdrawn
342	Feb-96		External Insulation and Finish Systems (R 287)	withdrawn 1/10/2001
341	Feb-96	nr	Protecting Valuable Records	withdrawn 1/01/2015
340	Feb-96	refer 520	Conservatories (R276)	withdrawn
339	Dec-95	refer tile GPG	Internal Wall Tiling	withdrawn 1/10/1996
338	Dec-95	refer 434	Rot in Timber	withdrawn 1/04/2003
337	Oct-95	refer 636	Protecting Window Glass from Surface Damage (R 236)	withdrawn 1/04/2019
336	Aug-95	refer 432	Building Papers, Wind Barriers and Vapour Barriers (R277)	withdrawn 1/06/2005
335	-1995	nr	Exposed Aggregate Precast Concrete Panels (R260)	withdrawn 1/01/2015
334	-1995	refer 427	Reducing Heat Losses From Existing Houses (R201)	withdrawn 1/05/2002
333	-1995	refer 469	Damp-proof Membranes to Concrete Slabs (R 274)	withdrawn 1/02/2006
332	-1995		Claddings in Corrosive Environments	withdrawn nr
331	-1995	refer 426, 461	Practical Sound Control (R180, 210, 211)	withdrawn 1/06/2005
330	-1995		Thin Flooring Materials- (2) Preparation and Laying (R 223)	withdrawn Dec 13 approx
329	-1995		Thin Flooring Materials - (1) Selection and Maintenance (R 222)	withdrawn Dec 13 approx
328	-1994	refer 453	Selection and Use of Fasteners	withdrawn 1/09/2004
327	-1994	nr	Open Fireplaces and Chimneys (R192)	withdrawn 19/6/2017
326	-1994	refer 407, 408	Cladding Buildings on Exposed Sites	withdrawn 1/01/2001
325	-1994	refer 405	Timber Framed Buildings on Exposed Sites (R 207)	withdrawn 1/11/2000
324	-1994	refer 381	Masonry Veneer Cladding - Detailing and Construction (R 94)	withdrawn 1/01/1999
323	-1994	nr	Glazing Plastics - (2) Design and Fixing (R 242)	withdrawn 30/11/17
322	-1994	nr	Glazing Plastics - (1) Types and Durability (R 241)	withdrawn 30/11/17
321	-1994	refer 620	Reducing the Impact of Wind at Building Sites (R 191)	withdrawn 10/4/2018
320	-1995	refer 495	Stair Design and Safety (R 256)	withdrawn 1/02/2008
319	-1994	refer 404	Subfloor Ventilation (R 245)	withdrawn 1/09/2000
318	-1994	refer 595	Care of Coil-Coated Metal Claddings (R 263)	withdrawn 28/1/2016
317	-1994	refer 488	Coil-coated Metal Claddings (R 261)	withdrawn 1/08/2007
316	-1993		Timber Strip Flooring and Internal Linings (R 170)	withdrawn nr
315	-1993		Wood Primers (R 257)	withdrawn nr
314	-1993	refer 633	Removing Paint From Houses	withdrawn 1/02/2019
313	-1993	refer 605	Domestic Glazing Safety	withdrawn 1/12/2016
312	-1993	pdf only	Reducing Heat Loss Through Windows. (R 224)	withdrawn
311	-1993	Refer 540	Use and Control of Solar Gain	withdrawn 1/10/2011
310	not issued			
309	-1993	refer 420	Fire Safety in Dwellings	withdrawn 1/09/2001
308	-1993	refer 455	Restoring a House After Flood Damage (R240)	withdrawn 1/11/2004
307	-1993	refer 420	Designing for Fire Safety (R 200)	withdrawn 1/09/2001
306	-1993	refer 654	Inspection Procedures for Chimneys, Fireplaces and Solid Fuel Appliances (R259)	withdrawn 1/10/2020
305	-1993	refer 448	Domestic Flashing Installation	withdrawn 1/04/2004
304	-1993	refer 467	Flashing Design	withdrawn 1/12/2005
303	-1992	refer 460	Moisture Control in Recreational Facilities	withdrawn 1/04/2005
302	-1992	refer 368	Constructing Timber Framed Skillion Roofs (R 111, 112, 113)	withdrawn 1/03/1998
301	-1993	refer GPG Internal Linings	Preventing Peaking and Popping Problems with Gypsum Plaster Board	withdrawn 19/6/2107
300	-1992		Plastic Piping - Installation	withdrawn nr
299	-1992		Plastic Piping - Types and Properties	withdrawn nr
298	-1992	refer 450	Solar Control Glass - Design and Installation Practice (R 265)	withdrawn 1/06/2004
297	-1992	refer 450	Solar Control Glass - Types and Properties (R 264)	withdrawn 1/06/2004

BRANZ Bulletin Index
11 Sep 2023

296	-1992		Transparent and Semi-transparent Exterior Finishes for Timber Exposed to the Weather (R 273)	withdrawn nr
295	-1992	refer 373	Specifying Timber (R 130)	withdrawn 1/07/1998
294	-1992	refer 371	Reconstituted Wood Board Sheet Flooring	withdrawn 1/05/1998
293	-1992	refer 344	Embedded Electric Floor Heating (R 179)	withdrawn 1/04/1996
292	-1992	refer 357	Thermal Insulation of Houses (R 169, 217, 233)	withdrawn 1/06/1997
291	-1992	refer 397	Basement Waterproofing - Selecting An Appropriate Membrane (R 38)	withdrawn 1/03/2000
290	-1992	refer 397	Basement Waterproofing - Design Principles (R 37)	withdrawn 1/03/2000
289	-1992	refer 385	Asphalt Shingle Roofing	withdrawn 1/05/1999
288	-1992		Timber Shingle and Shake Roofing	withdrawn 1/12/2003
287	-1991	refer 342	External Insulation and Finish Systems	withdrawn 1/02/1996
286	-1991	refer 422	Aluminium Windows – Design, Handling and Maintenance (R 225)	withdrawn 1/02/2002
285	-1991	refer 418	Designing for Thermal and Moisture Movement (R 70)	withdrawn 1/07/2001
284	-1991	refer 441	Sealed Joints in External Claddings - (2) Sealants (R 239)	withdrawn 1/10/2003
283	-1991	refer 440	Sealed Joints in External Claddings - (1) Joint Design (R 238)	withdrawn 1/10/2003
282	-1991		Glass Blocks - Materials and Installation	withdrawn nr
281	-1991		Glass Blocks - Selection and Design	withdrawn nr
280	-1991	refer 361	Weathergrooves	withdrawn 1/10/1997
279	-1991	refer 393	Powder-Powered Fastening Devices (R 149)	withdrawn 1/11/1999
278	-1991	refer 367	Preventing Dampness in Houses (R 243, 244)	withdrawn 1/03/1998
277	-1991	refer 336	Building Papers, Vapour Barriers and Wind Barriers (R125, 155)	withdrawn 1/08/1995
276	-1991	refer 340	Conservatories	withdrawn 1/02/1996
275	-1990	refer 386	Timber Treatment for Users and Specifiers (R 175)	withdrawn 1/05/1999
274	-1990	refer 333	Damp-proof Membranes to Concrete Slabs	withdrawn?? 95
273	-1990	refer 296	Transparent and Semi-transparent Exterior Finishes for Timber Exposed to the Weather (R 273)	withdrawn??92
272	-1990	refer 359, 379	Moisture in the Building Structure (R 215)	withdrawn 1/08/1997
271	-1990	refer 343	Changes in Moisture Content in Timber (R 25)	withdrawn 1/04/1996
270	-1990		Human Impact on Glass in High Rise Buildings	withdrawn
269	-1990	refer 382	Curing of Concrete (The) (R 59)	withdrawn 1/03/1999
268	-1990	refer 442	Efflorescence on Masonry (R32)	withdrawn 1/12/2003
267	-1989	refer 399	Timber Pile Foundations for Single Storey Light Timber Framed Buildings	withdrawn 1/05/2000
266	-1989	refer Good Tiling	Exterior Ceramic Wall Tiling	withdrawn
265	-1989	refer 298	Solar Control Glass - Design and Installation Practice	withdrawn
264	-1989	refer 297	Solar Control Glass - Types and Properties	withdrawn
263	-1989	refer 318	Care of Coil-Coated Metal Claddings	withdrawn
262	-1989	refer 376	Residential Fire Sprinklers	withdrawn1/09/1998
261	-1989	refer 317	Coil-Coated Metal Claddings	withdrawn
260	-1988	refer 335	Exposed Aggregate Precast Concrete Panels	withdrawn
259	-1988	refer 306	Inspection Procedures for Chimneys, Fireplaces and Solid Fuel Burning Appliances	withdrawn
258	-1987	refer 444	Lessons From the 1987 Edgcombe Earthquake	withdrawn 1/12/2003
257	-1987	refer 315	Wood Primers	withdrawn
256		refer 320	Stair Design and Safety	withdrawn
255	-1987		Polymer Concrete Floors	withdrawn
254	-1987	refer 332	Avoiding Corrosion Problems in Buildings	withdrawn
253	-1987	refer 377	Maintenance Painting of Coated Steel Structures	withdrawn 1/11/1998
252	-1987	refer 348	Domestic Smoke Alarms	withdrawn 1/07/1996
251	-1986	refer 350	Gutters and Downpipes (R140)	withdrawn 1/10/1996
250	-1986		Testing for Fire Resistance	withdrawn
249	-1986	Refer 362	Finishes on Architectural Hardware	withdrawn 1/10/1997
248	-1986		Solid Fuel Appliances: Their Use in Existing Fireplaces	withdrawn
247	(1985, 86)		Solid Fuel Stoves	withdrawn
246	-1985	refer 356	Adhesives for Use with Wood and Wood-based Products	withdrawn 1/06/1997
245	-1985	refer 319	Subfloor Ventilation	withdrawn
244	-1985	refer 278	Preventing Dampness in Houses 2: Condensation and Mildew (R216)	withdrawn
243	-1985	refer 278	Preventing Dampness in Houses 1: Underfloor Dampness	withdrawn

BRANZ Bulletin Index
11 Sep 2023

242	-1985	refer 323	Glazing Plastics 2: Design and Fixing	withdrawn
241	-1985	refer 322	Glazing Plastics 1: Types and Durability	withdrawn
240	-1984	refer 308	Restoring a House after Flood Damage	withdrawn
239	-1984	refer 284	Sealed Joints in External Claddings 2 - Sealants	withdrawn
238	-1984	refer 283	Sealed Joints in External Claddings 1 Joint Design	withdrawn
237	-1984	refer 338	Dry Rot in Timber (R17)	withdrawn
236	-1984	refer 337	Corrosion and Staining of Glass Windows	withdrawn
235	-1984	refer 358	Nail Fixing of Corrugated Steel Roofing	withdrawn 1/06/1997
234	-1983	refer 261	Coil-Coated Products: Information for Designers	withdrawn
233	-1983	refer 292	Insulating Suspended Timber Frame Floors	withdrawn
232	-1989	refer 352	Pole House Construction (1989)	withdrawn 1/12/1996
231	-1982	refer 363	Repairing Cracks in Concrete (R36)	withdrawn 1/01/1998
230	-1982		Stainless Steels for Building Claddings	withdrawn
229	-1981		Glass Fibre-reinforced Polyester Cladding Panels 2 Design, Durability and Maintenance	withdrawn
228	-1981		Glass Fibre-reinforced Polyester Cladding Panels 1 Materials and Manufacture	withdrawn
227	-1981		Weights and Sizes of Building Materials	withdrawn
226	-1981	refer 351	Corrosion of Reinforcing Steel	withdrawn 1/12/1996
225	-1981	refer 286	Aluminium Windows Do's and Don'ts	withdrawn
224	-1980	refer 312	Double Glazing	withdrawn
223	-1980	refer 330	PVC Flooring 2 Preparation and Laying (R 92)	withdrawn
222	-1980	refer 329	PVC Flooring 1 - Materials and Maintenance (R 92)	withdrawn
221	-1980	refer Good Tiling	Ceramic Tiled Floors - (2) Laying (R 73)	withdrawn
220	-1980	refer Good Tiling	Ceramic Tiled Floors - (1) Materials and Maintenance (R73)	withdrawn
219	-1980		Single Stack Drainage	withdrawn
218	(1979, 84)	refer 349	Use of Powder-coated Aluminium	withdrawn 1/08/1996
217	(1979, 81)	refer 292	Thermal Insulation of Houses	withdrawn
216	-1979	refer 272	Condensation (R109)	withdrawn
215	(1979	refer 272	Moisture Control in Buildings	withdrawn
214	-1979		Protection of Galvanised Steel Claddings	withdrawn
213	-1979	refer 349	Use of Anodised Aluminium	withdrawn 1/08/1996
212	-1979	refer 438	Soil Testing (with the Scala Penetrometer)	withdrawn 1/08/2003
211	-1978	refer 331	Noise Control in Flats - 2	withdrawn
210	-1978	refer 331	Noise Control in Flats - 1	withdrawn
209	-1978		Management Assistance for Small Companies	withdrawn
208	-1978	refer 257	Wood Primers	withdrawn
207	-1978	refer 325	Building on Windswept Sites	withdrawn
206	-1978	refer 232	Pole Frame Construction	withdrawn
205	(1978, 84)		Concrete Do's and Don'ts	withdrawn
204	-1978		CI/SfB Information Classification System	withdrawn
203	-1978	refer 332	Atmospheric Corrosion of Metals	withdrawn
202	-1978	refer 254	Avoiding Corrosion Problems in Buildings	withdrawn
201	-1977	refer 334	Reducing Heat Losses From Existing Houses	withdrawn
200	-1977	refer 307	Fire and Buildings - Control of Fire by Building Design	withdrawn
199	-1977		Case Histories	withdrawn
198	-1977		Fire and Buildings - Terminology and tests	withdrawn
197	-1977	refer 197A	Solar Water Heaters Installation	withdrawn
196	(1977, 79)		Solar Water Heaters Application	withdrawn
195	-1977	refer 207	Building on Windswept Sites	withdrawn
194	-1977		Weather and the Builder	withdrawn
193	(1976, 79)		Fireside Topics	withdrawn
192	-1977	refer 327	Open Fireplaces and Chimneys	withdrawn
191	(1976, 81)	refer 321	Wind - Selecting and Protecting a Site (R16)	withdrawn
190	-1976		Solar Control Glass Case Histories	withdrawn
189	(1976, 79)	refer 215	Moisture Control in Buildings	withdrawn
188	-1976	refer 265	Solar Control Glass Installation Practice	withdrawn
187	-1976		Storm Damage	withdrawn
186	-1976		Case Histories	withdrawn
185	-1976		Index to Bulletins	withdrawn
184	-1976	refer 227	Weights and Sizes of Building Materials	withdrawn
183	(1976,79)		Plumbing Do's and Don'ts	withdrawn

BRANZ Bulletin Index
11 Sep 2023

182	-1976	refer 217	Thermal Insulation of Houses	withdrawn
181	-1975		Control of Shower Temperature Fluctuations	withdrawn
180	(1975, 78)	refer 331	Acoustic Performance Requirements of Partitions	withdrawn
179	-1975	refer 293	Embedded Electric Floor Heating (R79)	withdrawn
178	-1975		Do's and Don'ts	withdrawn
177	-1975	refer 233	Building Foil Insulated Floors	withdrawn
176	-1974	refer 294	Particle Board Flooring	withdrawn
175	-1974	refer 275	Timber Preservation for the User	withdrawn
174	-1974		Metriation 3	withdrawn
173	-1973		Falls on Building Sites	withdrawn
172	-1973		Plywood Flooring	withdrawn
171	-1973		Stainless Steel Water Tanks	withdrawn
170	-1973	refer 316	Timber Vertical Boarding	withdrawn
169	-1973	refer 292	Correct Use of Foil Insulation in Walls (The)	withdrawn
168	-1973		Squeaky Floors	withdrawn
167	-1973		Corrosion of Copper Pipe in Housing	withdrawn
166	-1973		On-Site Precasting - Tilt up Part 2	withdrawn
165	-1973		On-Site Precasting - Tilt up Part 1	withdrawn
164	-1973		Cost of Labour (The)	withdrawn
163	(1973, 78)		Sound Absorbers and their Use	withdrawn
162	-1973		Joists, Floor Beams and Lintels for Small Buildings	withdrawn
161	(1972, 80)		Formwork Release Agents	withdrawn
160	-1972		Index to Bulletins	withdrawn
159	-1972		Pumping Concrete	withdrawn
158	(1972, 78)	refer 239	Putties Mastics and Sealants 2	withdrawn
157	(1972, 78)	refer 238	Putties Mastics and Sealants 1	withdrawn
156	-1972		Change to Metric in the Building Industry	withdrawn
155	-1972	refer 277	Building Papers and Membranes	withdrawn
154	(1972, 80)		Plastering (3) Internal Walls and Ceilings	withdrawn
153	-1972		Design for Mass Housing	withdrawn
152	(1972, 77)		Concrete Ground Floor Slabs	withdrawn
151	-1972		Timber Formwork for Concrete	withdrawn
150	-1972		Building Bylaws and Regulations	withdrawn
149	-1971	refer 279	Powder-Powered Tools	withdrawn
148	-1971		How to Keep Comfortable in Buildings	withdrawn
147	-1971		Plastering 2 - External Walls	withdrawn
146	-1971	refer 214	Galvanised Corrugated Steel and its Protection	withdrawn
145	-1971		Plastering 1 - General Practices and Problems	withdrawn
144	-1971		Do's and Don'ts No 7	withdrawn
143	-1971		Good Lighting in Buildings	withdrawn
142	-1971	refer 324	Masonry Veneer Construction	withdrawn
141	-1971	refer 204	CI/SfB Information Classification System	withdrawn
140	-1971	refer 251	Gutters Spouting and Downpipes	withdrawn
139	-1971		Concrete Floor Finishes and Toppings	withdrawn
138	-1971		Metric Conversion	withdrawn
137	-1970		Metric Conversion	withdrawn
136	-1970		Surface Spread of Flame	withdrawn
135	-1970		Wind Loads: Some Problem and Design Aspects	withdrawn
134	-1970		CPM: Building and Construction Some Useful Developments	withdrawn
133	-1970		CPM fro Building and Construction Management	withdrawn
132	-1970		Acoustic Insulation Properties of Partitions in Buildings	withdrawn
131	-1970		Care of Materials on Site	withdrawn
130	(1970, 77)	refer 295	Specifying Timber - Species and Grade	withdrawn
129	-1970		Timber Shrinkage in New Buildings	withdrawn
128	-1970		Continuity of Publication	withdrawn
127	-1970		Concrete Blocks for Houses	withdrawn
126	-1970		External Walls: Principles and Practice	withdrawn
125	-1969	refer 277	Vapour Barriers	withdrawn
124	-1969		Fire Resistance Ratings	withdrawn
123	-1969	refer 360	Level Surfaces on Concrete Floors under Thin Flooring	withdrawn 1/08/1997
122	-1969	refer 219	Single Stack Drainage	withdrawn
121	-1969	refer 249	Metal Hardware Finishes	withdrawn

BRANZ Bulletin Index
11 Sep 2023

120	-1969		<i>Thermal Resistance</i>	<i>withdrawn</i>
119	-1969		<i>Recommendations for the Painting of Buildings</i>	<i>withdrawn</i>
118	-1969	refer 176	<i>Particle Board Flooring</i>	<i>withdrawn</i>
117	-1969		<i>Metric System (The)</i>	<i>withdrawn</i>
116	-1969		<i>Masonry Cladding</i>	<i>withdrawn</i>
115	-1969		<i>Organic Surface Coatings</i>	<i>withdrawn</i>
114	-1969	refer 216	<i>Risk of Condensation (The) (R109)</i>	<i>withdrawn</i>
113	-1968	refer 302	<i>Sloping Compact Roofs</i>	<i>withdrawn</i>
112	(1968, 77)	refer 302	<i>Flat Compact Roofs - Practice</i>	<i>withdrawn</i>
111	(1968, 77)	refer 302	<i>Flat Compact Roofs - Problems</i>	<i>withdrawn</i>
110	-1968		<i>Vapour Diffusion</i>	<i>withdrawn</i>
109	-1968	refer 216	<i>Condensation</i>	<i>withdrawn</i>
108	-1968		<i>Accuracy and Tolerances - Part 3</i>	<i>withdrawn</i>
107	-1968		<i>Accuracy and Tolerances - Part 2</i>	<i>withdrawn</i>
106	-1968		<i>Accuracy and Tolerances - Part 1</i>	<i>withdrawn</i>
105	-1968		<i>Pitched Roofs Performance Requirements</i>	<i>withdrawn</i>
104	-1968		<i>Sources of Electric Light</i>	<i>withdrawn</i>
103	-1968		<i>Airflow Around Buildings</i>	<i>withdrawn</i>
102	-1968		<i>Solar Water Heating for Domestic Use</i>	<i>withdrawn</i>
101	-1967		<i>Lightweight Concrete 6 - Sawdust Concrete</i>	<i>withdrawn</i>
100	(1967, 77)		<i>Availability of Daylight for Building Design</i>	<i>withdrawn</i>
99	-1967		<i>Lightweight Concrete 5 Artificial Aggregates - Perlite</i>	<i>withdrawn</i>
98	-1967		<i>Gypsum Products - Their Behaviour in Fire</i>	<i>withdrawn</i>
97	-1967		<i>Lightweight Concrete 4 Artificial Aggregates - Vermiculite</i>	<i>withdrawn</i>
96	-1967		<i>Lightweight Concrete 3 No-fines Concrete</i>	<i>withdrawn</i>
95	-1967		<i>Weatherproof Jointing</i>	<i>withdrawn</i>
94	(1967, 77)	refer 142	<i>Cavity Wall Construction</i>	<i>withdrawn</i>
93	-1967		<i>Glazing Design</i>	<i>withdrawn</i>
92	-1967	refer 222,223	<i>PVC Flooring (R22)</i>	<i>withdrawn</i>
91	-1967		<i>Solar Radiation Through Vertical Glass</i>	<i>withdrawn</i>
90	-1967		<i>Do's and Don'ts No 6</i>	<i>withdrawn</i>
89	-1966		<i>Battery Casting of Concrete Panels</i>	<i>withdrawn</i>
88	-1966		<i>Lightweight Concrete 2 - Pumice Concrete</i>	<i>withdrawn</i>
87	-1966	refer 299, 300	<i>Unplasticised PVC Pipe</i>	<i>withdrawn</i>
86	-1966		<i>Lightweight Concrete 1 - Aerated Concrete</i>	<i>withdrawn</i>
85	-1966		<i>House Construction - Critical Path Planning</i>	<i>withdrawn</i>
84	-1966		<i>Do's and Don'ts No 5</i>	<i>withdrawn</i>
83	-1966	refer 331	<i>Practical Noise Control for Timber Framed Buildings</i>	<i>withdrawn</i>
82	-1966		<i>Internal Wood Flooring Naturally Finished</i>	<i>withdrawn</i>
81	-1966		<i>Behaviour of Curtain Walling in Fire (The)</i>	<i>withdrawn</i>
80	-1966	refer 230	<i>Stainless Steel for Buildings</i>	<i>withdrawn</i>
79	-1966	refer 293	<i>Electric Floor Heating – 2 (R24)</i>	<i>withdrawn</i>
78	-1966		<i>Do's and Don'ts No 4</i>	<i>withdrawn</i>
77	-1965		<i>Uses of Lime in Buildings - 2 (The)</i>	<i>withdrawn</i>
76	-1965		<i>Uses of Lime in Buildings - 1 (The)</i>	<i>withdrawn</i>
75	-1965	refer 359	<i>Rain Penetration</i>	<i>withdrawn</i>
74	-1965		<i>Mastics and Gaskets</i>	<i>withdrawn</i>
73	-1965	refer 220, 221	<i>Ceramic Tiled Floors</i>	<i>withdrawn</i>
72	-1965		<i>Do's and Don'ts No 3</i>	<i>withdrawn</i>
71	-1965	refer 182	<i>Thermal Insulation of Houses</i>	<i>withdrawn</i>
70	-1965	refer 285	<i>Dimensional Changes in Building Materials</i>	<i>withdrawn</i>
69	-1965	refer 94	<i>Damp-Course for Masonry Walls (A)</i>	<i>withdrawn</i>
68	-1965		<i>Mould Stains on Timber</i>	<i>withdrawn</i>
67	-1965	refer 437	<i>Mould in Dwellings</i>	<i>withdrawn 1/06/2003</i>
66	-1965		<i>Concrete Admixtures</i>	<i>withdrawn</i>
65	-1964		<i>Sound Insulating Floors in Buildings - 1</i>	<i>withdrawn</i>
64	-1964	refer 246	<i>Adhesives for the Building Industry</i>	<i>withdrawn</i>
63	-1964		<i>Design of Modern Kitchens (The)</i>	<i>withdrawn</i>
62	-1964		<i>Wire Nails for Building Purposes</i>	<i>withdrawn</i>
61	-1964		<i>Roof Vents for the Control of Fire</i>	<i>withdrawn</i>
60	-1964		<i>Isolating Transformers</i>	<i>withdrawn</i>
59	-1964	refer 269	<i>Curing of Concrete (The)</i>	<i>withdrawn</i>

BRANZ Bulletin Index
11 Sep 2023

58	-1964	refer 316	Timber Flooring	withdrawn
57	-1964		Do's and Don'ts No 2	withdrawn
56	-1964		Trade Literature for the Building Industry: Its Classification and Storage	withdrawn
55	-1964		Metal Roofing Systems	withdrawn
54	-1964		Electric Wiring Regulations 1961	withdrawn
53	-1963		Wood Screws	withdrawn
52	-1963		Silicone Water Repellents	withdrawn
51	-1963		Do's and Don'ts	withdrawn
50	(1963, 66)		Model Building Bylaw (The)	withdrawn
49	-1963	refer 260	Exposed Aggregate Facing Panels	withdrawn
48	-1963		House Foundations on Unstable Soil	withdrawn
47	-1963		Noise Control Within a Room	withdrawn
46	(1963, 66)		Built-up Roofing	withdrawn
45	(1963, 66)		Fair Face Finish to Concrete	withdrawn
44	(1963, 66)		Formwork for Concreting	withdrawn
43	-1963		Permanent Supplementary Lighting in Offices	withdrawn
42	(1963, 66)		Plumbing for Tall Buildings	withdrawn
41	(1962, 66)		Mis-use of Metals in Buildings: Corrosion (The)	withdrawn
40	-1962	refer 143	Good Lighting in Buildings	withdrawn
39	-1962	refer 145, 147	Plastering on Concrete	withdrawn
38	(1962, 66)	refer 291	Waterproofing of Basements (Tanking) - 2	withdrawn
37	(1962, 66)	refer 290	Waterproofing of Basements (Tanking) - 1	withdrawn
36	-1962	refer 231	Repairing Cracks in Concrete	withdrawn
35	-1962		Recommended Glazing Sizes in High Winds (R22)	withdrawn
34	-1962		Warm Air Curtains	withdrawn
33	-1962	refer 142	Masonry Veneer Construction	withdrawn
32	-1962	refer 268	Efflorescence of Masonry	withdrawn
31	(1962, 66)		Plastic Formwork for Concrete	withdrawn
30	-1962		Building Materials and Fire	withdrawn
29	-1961	refer 132	Sound Insulating Partitions in Buildings	withdrawn
28	-1961		Building Research in Australia	withdrawn
27	(1961, 77)		Domestic Electric Power Supply	withdrawn
26	(1961, 66)	refer 92	Floor Coverings on Concrete Slabs	withdrawn
25	(1961, 66)	refer 271	Changes in the Moisture Content of Timber	withdrawn
24	-1961	refer 79	Electric Floor Heating	withdrawn
23	(1961, 66)	refer 274	Dampproof Membranes to Concrete Slabs	withdrawn
22	-1961	refer 35	Safe Glazing Sizes in High Wind	withdrawn
21	-1961		Finishing of Concrete Floors (The)	withdrawn
20	(1961, 66)		Present Day Paint and its Use	withdrawn
19	-1966		Good Concrete for the Small Builder	withdrawn
18	(1961, 66)	refer 191	Beware of the Wind	withdrawn
17	(1960, 77)	refer 237	Dry Rot in Timber	withdrawn
16	(1960, 66)	refer 217	Thermal Insulation for Buildings	withdrawn
15	-1960	refer 215	Dampness in Buildings	withdrawn
14	(1960, 66)	refer 206	Paint Protection of Iron and Steel against Corrosion	withdrawn
13	-1960		Fire Protection of Buildings	withdrawn
12	(1960, 66)	refer 140	Spouting and Downpiping	withdrawn
11	-1960	refer 225	Glazing into Aluminium	withdrawn
10	-1960	refer 224	Double Windows	withdrawn
9	(1960, 66)	refer 214	Galvanised Corrugated Roofing Iron	withdrawn
8	-1960	refer 155	Waterproof Building Papers	withdrawn
7	(1960, 66)	refer 273	Clear Finishes for External Timberwork	withdrawn
6	-1960	refer 175	Timber Preservation for the User	withdrawn
5	-1966		Fire Hazards with Slow Combustion Stove Installation	withdrawn
4	-1966		Aids to Concreting	withdrawn
3	(1959, 66)		Use of Radiata Pine in Construction (The)	withdrawn
2	-1959	refer 286	Aluminium Window Frames	withdrawn
1	-1959		New Materials a Cautionary Tale	withdrawn

BRANZ Bulletin Index
11 Sep 2023