

**BRANZ Bulletin Index**  
**19 Mar 2024**

Titles in **Bold** are current Bulletins

Titles in *Italics* indicate Bulletins that have been withdrawn

Bulletins are available as a downloadable PDFs from the BRANZ shop. Withdrawn bulletins are available from the BRANZ library service.

nr = bulletin withdrawn, no replacement

(RXXX) refers to the bulletin the title replaced

No.	Issued	New Number	Title	
<b>690</b>	<b>Mar-24</b>		<b>Thermal bridges in external wall framing</b>	
<b>689</b>	<b>Jan-24</b>		<b>Water heating systems (R586)</b>	
<b>688</b>	<b>Jan-24</b>		<b>Embedded floor heating (R577)</b>	
<b>687</b>	<b>Nov-23</b>		<b>Introduction to smart homes</b>	
<b>686</b>	<b>Sep-23</b>		<b>Building with 140 mm timber exterior wall framing</b>	
<b>685</b>	<b>Jul-23</b>		<b>Insulation of concrete slab-on-ground floors less than 300 m2</b>	
<b>684</b>	<b>May-23</b>		<b>Thermal modelling tools for houses</b>	
<b>683</b>	<b>May-23</b>		<b>The rules for sleepouts that don't need a building consent</b>	
<b>682</b>	<b>Mar-23</b>		<b>Specifying glazing</b>	
<b>681</b>	<b>Mar-23</b>		<b>Introduction to engineered wood products (EWPs)</b>	
<b>680</b>	<b>Dec-22</b>		<b>Insulating glass units (IGUs) (R598)</b>	
<b>679</b>	<b>Dec-22</b>		<b>Introduction to calculating whole-of-life carbon footprint of houses</b>	
<b>678</b>	<b>Dec-22</b>		<b>H1 Calculation method - housing, and buildings upto 300 m2 (R613)</b>	
<b>677</b>	<b>Oct-22</b>		<b>Specifying roofs under H1</b>	
<b>676</b>	<b>Oct-22</b>		<b>Complying with H1-Housing, and buildings up to 300 m2 (R668)</b>	
<b>675</b>	<b>Aug-22</b>		<b>Using a scala penetrometer (R438)</b>	
<b>674</b>	<b>Aug-22</b>		<b>Seismic retrofitting houses with piled foundations on sloping sites</b>	
<b>673</b>	<b>Jun-22</b>		<b>Cavity battens (582)</b>	
<b>672</b>	<b>Jun-22</b>		<b>Specifying floors under H1</b>	<i>Minor updates Oct-22</i>
<b>671</b>	<b>Apr-22</b>		<b>Reducing construction and demolition waste (R523)</b>	
<b>670</b>	<b>Apr-22</b>		<b>Specifying windows and doors under H1</b>	<i>Minor updates Oct-22</i>
<b>669</b>	<b>Feb-22</b>		<b>Tools for measuring carbon in new-build houses</b>	
<i>668</i>	<i>Feb-22</i>	<i>refer 676</i>	<i>Complying with H1-Housing, and buildings up to 300 m2</i>	<i>Withdrawn Oct-22</i>
<b>667</b>	<b>Dec-21</b>		<b>Earth buildings</b>	
<b>666</b>	<b>Dec-21</b>		<b>Restoring a home after flood damage (R455)</b>	
<b>665</b>	<b>Aug-21</b>		<b>Residential greywater systems</b>	
<b>664</b>	<b>Aug-21</b>		<b>Residential rainwater systems</b>	
<b>663</b>	<b>Jun-21</b>		<b>Universal design for access into homes by vehicle</b>	
<b>662</b>	<b>Jun-21</b>		<b>Universal design for access into homes</b>	
<i>661</i>	<i>Apr-21</i>		<i>Residential Roofs with High Thermal Performance</i>	<i>Withdrawn Oct-22</i>
<i>660</i>	<i>Apr-21</i>		<i>Residential Walls with High Thermal Performance</i>	<i>Withdrawn Oct-22</i>
<b>659</b>	<b>Feb-21</b>		<b>Upgrading the Thermal Performance of Timber Windows (R507)</b>	
<b>658</b>	<b>Feb-21</b>		<b>Timber Windows (R481)</b>	
<b>657</b>	<b>Dec-20</b>		<b>Designing Water-efficient Houses</b>	
<i>656</i>	<i>Dec-20</i>		<i>Designing to Avoid Houses Overheating</i>	<i>Withdrawn Oct-22</i>
<i>655</i>	<i>Oct-20</i>		<i>Building Blocks for New-build Net-zero Carbon Houses</i>	<i>Withdrawn Oct-22</i>
<b>654</b>	<b>Oct-20</b>		<b>Installation and Maintenance of Solid Fuel Appliances (R306)</b>	
<i>653</i>	<i>Oct-20</i>		<i>Damp-proof Membranes to Concrete Slabs (R469)</i>	<i>Withdrawn Oct-22</i>
<b>652</b>	<b>Aug-20</b>		<b>Amendments to Acceptable Solutions and Verification Methods for B1 and E2 (R545)</b>	
<b>651</b>	<b>Jun-20</b>		<b>Climate Change, Net-Zero Carbon and the Building Industry</b>	
<i>650</i>	<i>Jun-20</i>	<i>nr</i>	<i>Building Beyond Code Minimums</i>	<i>Withdrawn Oct-22</i>
<b>649</b>	<b>Apr-20</b>		<b>Corrosion of Metals in New Zealand Buildings</b>	
<b>648</b>	<b>Apr-20</b>		<b>Timber Shingle and Shake Roofing (R443)</b>	
<b>647</b>	<b>Feb-20</b>		<b>Recessed Luminaires (R539)</b>	
<b>646</b>	<b>Feb-20</b>		<b>Floor Levelling Compounds (R360)</b>	
<b>645</b>	<b>Dec-19</b>		<b>Installing Timber Strip Flooring over Timber Joists (R390)</b>	
<b>644</b>	<b>Dec-19</b>		<b>Solid Timber Strip Flooring on a Concrete Slab (R506)</b>	
<b>643</b>	<b>Dec-19</b>		<b>Energy Efficiency in New Zealand Houses</b>	

**BRANZ Bulletin Index**  
**19 Mar 2024**

642	Dec-19		Changes in the Condition of New Zealand Houses over 25 Years	
641	Aug-19		Concrete Toppings (R389)	
640	Aug-19		Metal Component Terminology (R490)	
639	Jun-19		Domestic Active Fire Protection (R458)	
638	Jun-19		Finishes on Architectural Hardware (R362)	
637	Apr-19		Domestic On-Site Foulwater Treatment (R485)	
636	Apr-19		Protecting Glass from Damage (R337)	Minor update Dec-22
635	Feb-19		Bracing Distribution	
634	Feb-19		Finishing Aluminium (R349)	
633	Feb-19		Removing Paint Coatings (R314)	
632	Dec-18		Planning for Maintenance (R479)	Minor update Dec-22
631	Dec-18		How Micro-environments Affect Material Performance	
630	Dec-18		Roof Space Ventilation	
629	Oct-18	nr	ALF 4.0 Building Performance Index Calculator (R555)	Withdrawn Oct-22
628	Oct-18		Sheet Flooring (R371)	
627	Aug-18		The Impact of Geothermal Environments on Metals and Wood	
626	Aug-18		Slip Resistance of Floors (R370)	
625	Aug-18		Stair Design (R495)	
624	Jun-18		An Introduction to WUFI	
623	Jun-18		Curing Concrete (R382)	
622	Apr-18		Good Plans and Specifications (R505)	
621	Apr-18		Site Practices (R499)	
620	Apr-18		Managing Wind Effects Around Buildings (R321)	
619	Feb-18		House Condition Survey 2015	
618	Feb-18		Acoustic Design Principles (R426)	
617	Dec-17		Subfloor and Roof Bracing in NZS 3604:2011 Buildings	
616	Dec-17		Wall Bracing in NZS 3604:2011 Buildings	
615	Oct-17		Critical Connections	
614	Oct-17	nr	H1 Compliance Options (R522)	Withdrawn Oct-22
613	Aug-17	refer 678	NZS 4218:2009 Calculation Method (R504)	Withdrawn Oct-22
612	Aug-17		Load Paths	
611	Jun-17		Timber Slat Decks (R489)	
610	Jun-17		Preventing Moisture Problems in Timber-framed Skillion Roofs (R525)	
609	Apr-17		Photovoltaic Systems for Dwellings	
608	Apr-17		Building Life Cycle Assessment	
607	Feb-17		Passive Ventilation (R430)	
606	Feb-17		Residential Fire Safety (R420)	
605	Dec-16		Residential Glazing Safety (R313)	Withdrawn Oct-22
604	Dec-16		Vapour Control in New Zealand buildings	
603	Oct-16		Environmental Product Declarations	Minor update Mar-23
602	Oct-16		Thermal Modelling Tools for Houses	Withdrawn Oct-22
601	Aug-16		Sealants for Cladding Joints (R441)	
600	Aug-16		Heat Pumps (R473)	
599	Jun-16		Solar-control Glazing (R450)	Withdrawn Oct-22
598	Jun-16	refer 680	Insulating Glass Units (IGUs) (R471)	Withdrawn Oct-22
597	Apr-16		Timber Pole House Construction (R459)	
596	Apr-16		An Introduction to Life Cycle Assessment	
595	Feb-16		Factory-coated Metal Claddings (R318 and 488)	
594	Feb-16		Excessive Moisture in Enclosed Subfloor Spaces (R457)	
593	Feb-16		Efflorescence (R442)	
592	Dec-15		Concrete Slab-on-Ground Floors (R372)	Withdrawn Oct-22
591	Dec-15		Waterproofing Tiled Showers	
590	Oct-15		Contracts in the Building Industry (R580)	
589	Oct-15		Heat Pump Water Heating (R529)	
588	Oct-15		BRANZ Maps and Wind Zone Calculations	Minor update Mar-23
587	Aug-15		Dealing with Construction Moisture in New Buildings (R447)	
586	Aug-15		Embedded Floor Heating (R491)	Withdrawn January 2024
585	Jun-15		Measuring Moisture in Timber and Concrete (R515)	
584	Jun-15		Sealed Joint Design – Claddings (R440)	

**BRANZ Bulletin Index**  
**19 Mar 2024**

583	Apr-15		<b>Waterproof Decks (R472)</b>	
582	Apr-15	refer 673	<b>Structurally Fixed Cavity Battens (R475)</b>	Withdrawn Jun-2022
581	Feb-15		<b>Residential Mechanical Ventilation Systems (R484 and 508)</b>	
580	Feb-15	refer 590	<i>Contracts in the Building Industry (R409)</i>	Withdrawn 30/9/2015
579	Dec-14	nr	<i>Windows Energy Efficiency Rating System (WEERS) (R474)</i>	Withdrawn Oct-22
578	Dec-14		<b>Ventilation Drying Behind Wall Claddings</b>	
577	Oct-14		<i>Water Heating Systems (R480)</i>	Withdrawn January 2024
576	Oct-14		<i>Edge Insulation of Concrete Floor Slabs (R552)</i>	Withdrawn Oct-22
575	Aug-14		<b>Timber Treatment (R538)</b>	
574	Aug-14		<b>Preventing Corrosion of Reinforcing Steel in Concrete (R464)</b>	
573	Jun-14		<b>Flexible Wall Underlays (R470)</b>	
572	Jun-14		<b>Aggravated Thermal Bridging Research</b>	
571	Apr-14		<b>Thermal Mass</b>	
570	Apr-14		<b>Ground Clearances (R353)</b>	
569	Feb-14		<b>Metal-clad Insulated Panels</b>	
568	Feb-14		<b>Low-impact Homes (R446)</b>	
567	Dec-13		<b>E2/AS1 Flashing Requirements (R465/467)</b>	
566	Dec-13		<b>Applied Window Films (R421)</b>	
565	Sep-13		<b>Canterbury Earthquakes Royal Commission: Key Recommendations</b>	
564	Sep-13		<b>Trombe Walls</b>	
563	Aug-13		<b>Building on Exposed Sites (R405, 406, 407, 408)</b>	
562	Aug-13		<b>Low Retaining Walls (R394)</b>	
561	May-13		<b>Timber-Framed Parapets, Balustrades and Columns (R466)</b>	
560	May-13		<b>Pile Foundations (R399)</b>	
559	Apr-13		<b>Pre-Purchase Inspections (R423)</b>	
558	Apr-13		<b>Earthquake Terminology</b>	
557	Feb-13		<b>Timber Framed Garages (R395)</b>	
556	Feb-13		<b>Internal Gutter Design (R537)</b>	
555	Nov-12	refer 629	<i>A Guide to ALF 3.2</i>	withdrawn 28/9/2018
554	Nov-12		<i>Aluminium Joinery Installation in Direct-fixed Cladding (R452, 463)</i>	Withdrawn Oct. 2022
553	Oct-12		<i>Aluminium Joinery Installation in Cavity Construction (R452, 463)</i>	Withdrawn Oct. 2022
552	Oct-12	refer 576	<i>Edge Insulation of Concrete Floor Slabs</i>	withdrawn 1/09/2014
551	Aug-12		<b>Learnings from the Canterbury Earthquakes</b>	
550	Aug-12		<b>Damage from Weathertightness Failure (R434)</b>	
549	Jun-12		<i>Lintels and Beams Calculator</i>	withdrawn 1/8/2020
548	Jun-12		<b>Repairing Plasterboard After an Earthquake</b>	
547	Apr-12		<i>Selecting Glass (R419)</i>	Withdrawn Oct-22
546	Apr-12		<b>House Condition Survey – External envelope</b>	
545	Feb-12	refer 652	<i>Key Changes to B1/AS1 and E2/AS1 (R542)</i>	withdrawn 1/08/2020
544	Feb-12		<i>BRANZ Appraisals</i>	withdrawn 1/04/2021
543	Feb-12		<b>Concrete Finishes</b>	
542	Dec-12	refer 545	<i>Key Changes to B1/AS1 and E2/AS1</i>	withdrawn 1/02/2012
541	Dec-11		<b>Concrete Floor Slabs</b>	
540	Oct-11		<i>Solar Gain in Housing (R311)</i>	Withdrawn Oct-22
539	Oct-11	refer 647	<i>Recessed Downlights (R482)</i>	withdrawn 1/2/2020
538	Aug-10	refer 575	<i>Timber Treatment (R493)</i>	withdrawn 1/07/2014
537	Aug-11	refer 556	<i>Internal Gutter Design</i>	withdrawn 1/02/2013
536	Jun-11		<b>Upgrading Piled Foundations to Resist Earthquakes</b>	
535	Jun-11		<b>Repairing Cracks in Concrete (R363)</b>	
534	Apr-11		<b>Overlay Flooring Systems Over a Suspended Floor</b>	
533	Apr-11		<b>Green Roofs</b>	
532	Feb-11		<b>Site Records (R391)</b>	
531	Feb-11		<b>Designing for Thermal and Moisture Movement (R418)</b>	
530	Dec-10		<b>Strawbale Construction (R398)</b>	
529	Dec-10		<i>Heat Pump Water Heating</i>	withdrawn 30/9/2015
528	Oct-10		<b>Metal Tile Roofing</b>	
527	Oct-10		<b>Drained and Vented Cavities</b>	
526	Aug-10		<b>Specifying Timber (R451)</b>	
525	Aug-10	refer 610	<i>Preventing Moisture Problems in Timber-framed Skillion Roofs</i>	withdrawn 31/5/2017

**BRANZ Bulletin Index**  
**19 Mar 2024**

<b>524</b>	<b>Jun-10</b>		<b>Solar Water Heating (R477)</b>	
523	Jun-10	refer 671	Reducing Waste from Building Sites (R383)	withdrawn 1/04/2022
522	Apr-10	refer 614	H1 Compliance Options	withdrawn 1/10/2017
<b>521</b>	<b>Apr-10</b>		<b>Squeaky Floors</b>	
<b>520</b>	<b>Feb-10</b>		<b>Conservatories (R340)</b>	
<b>519</b>	<b>Feb-10</b>		<b>Fasteners Selection (R453)</b>	
<b>518</b>	<b>Dec-09</b>		<b>Wet Area Tile Waterproofing</b>	
517	Dec-09		Passive Fire Protection – Maintenance and On-going Compliance	withdrawn 20/08/20
<b>516</b>	<b>Oct-09</b>		<b>Moisture Management in Masonry Veneer</b>	
515	Oct-09	refer 585	Measuring Moisture in Timber and Concrete (R424)	withdrawn 1/05/2015
514	Aug-09		Passive Fire Protection – On Site Installation	withdrawn 20/08/20
<b>513</b>	<b>Aug-09</b>		<b>Timber Composite Overlay Flooring</b>	
512	Jun-09		Passive Fire Protection – Roles and Responsibilities	withdrawn 20/08/20
<b>511</b>	<b>Jun-09</b>		<b>Residential Roof Drainage Design</b>	
510	Apr-09		Introduction to Passive Fire Design	withdrawn 20/08/20
<b>509</b>	<b>Apr-09</b>		<b>Sizing Gutters and Downpipes (R350)</b>	
508	Feb-08	refer 581	Heat Recovery Ventilation Systems	withdrawn 1/01/2015
507	Feb-08	refer 659	Retrofit Glazing of Timber Windows	withdrawn 1/02/2021
506	Nov-08	refer 644	Laying Solid Timber Strip Flooring on Concrete Slabs (R374)	withdrawn 1/12/2019
505	Nov-08	refer 622	Acceptable Plans and Specifications (R365)	withdrawn 10/4/2018
504	Oct-08	refer 613	NZS 4218 Calculation Method	withdrawn 31/7/17
<b>503</b>	<b>Oct-08</b>		<b>Rainwater Harvesting in Commercial and Industrial Buildings</b>	
502	Aug-08	nr	On-site Sequencing	withdrawn 30/11/17
501	Aug-08	refer Building Basics Insulation	Insulating Suspended Timber Floors	withdrawn 19/6/2017
500	Aug-08	nr	Optimising Energy Efficient Design of Houses	withdrawn 30/11/17
499	Jun-08	refer 621	Site Practices	withdrawn 10/4/2018
<b>498</b>	<b>Jun-08</b>		<b>Preparation for Concrete Floor Slabs</b>	
<b>497</b>	<b>Apr-08</b>		<b>Stair Construction</b>	
496	Apr-08	refer Building Basics Insulation and GRG Retrofitting Wall Insulation	Retrofitting Thermal Insulation	withdrawn 19/6/2017
495	Feb-08	refer 625	Stair Design (R320)	withdrawn 27 July 2018
494	Feb-08	refer Building Basics Insulation	Thermal Insulation of New Houses (R357)	withdrawn 19/6/2017
493	Dec-07	refer 538	Timber Treatment (445)	withdrawn 1/08/2011
492	Dec-07		Slab on Ground Insulation	withdrawn 1/02/2014
491	Oct-07	refer 586	Embedded Floor Heating	withdrawn 1/11/2013
490	Oct-07	refer 640	Metal Component Terminology	withdrawn 31/7/19
489	Aug-07	refer 611	Timber Slat Decks/Balconies (R483)	withdrawn 1/11/2013
488	Aug-07	refer 595	Coil Coated Metal Cladding (R 317)	withdrawn 28/1/2016
487	Aug-07	nr	Fencing Swimming Pools, Spas and Hot Tubs (R392)	withdrawn 19/6/2017
<b>486</b>	<b>May-07</b>	<b>pdf only</b>	<b>BRANZ Household Energy End-use Project</b>	
485	May-07	refer 637	Domestic On-Site Wastewater Treatment (R400)	withdrawn 1/04/2019
484	Apr-07	refer 581	Mechanical Home Ventilation Systems	withdrawn 1/01/2015
483	Apr-07	refer 489	Timber Slat Decks (R462)	withdrawn 1/06/2007
482	Feb-07	refer 539	Downlights	withdrawn 1/10/2011
481	Feb-07	refer 658	Timber Windows	withdrawn 1/02/2021
480	Dec-06	refer 577	Water Heating Systems	withdrawn 1/09/2014
479	Dec-06	refer 632	Planning For Maintenance	withdrawn 30/11/18
478	Oct-06	refer www.level.org.nz and GRG Rainwater Storage Systems	Rainwater Collection for Domestic Use	withdrawn 19/6/2017
477	Oct-06	refer 524	Solar Water Heating	withdrawn 1/06/2010
476	Aug-06	nr	Natural Stone Veneers	withdrawn 21/8/2015
475	Aug-06	refer 582	Structurally Fixed Cavity Battens	withdrawn 1/03/2015
474	Jun-06		WERS -- Window efficiency rating system	withdrawn 1/11/2014

**BRANZ Bulletin Index  
19 Mar 2024**

473	Jun-06	refer 600	Heat Pumps	withdrawn 1/8/2016
472	Apr-06	refer 583	Waterproof Decks	withdrawn 1/03/2015
471	Apr-06	refer 598	Insulating Glass Units (R387)	withdrawn 1/6/2016
470	Feb-06	refer 573	Wall Underlays (432)	withdrawn 7/10/2013
469	Feb-06	refer 653	Dampproof Membranes to Concrete Slabs (R333)	withdrawn 1/10/2020
<b>468</b>	<b>Dec-05</b>		<b>Fixing Timber weatherboards (R416)</b>	
467	Dec-05	refer 567	Principles of Flashing design (R304)	withdrawn 1/12/2013
466	Sep-05	refer 561	Timber-Framed Parapets, Balustrades and Columns (R415)	withdrawn 1/05/2013
465	Sep-05	refer 567	Domestic Flashing Installation (R305)	withdrawn 1/12/2013
464	Jul-05	refer 574	Prevention of Corrosion in Reinforcing Steel (R351)	withdrawn 1/07/2014
463	Jul-05	refer 553, 554	Aluminium Windows and E2/AS1 (R366)	withdrawn 1/11/2012
462	Jul-05	refer 483	Constructing Timber Decks (R355)	withdrawn 1/04/2007
<b>461</b>	<b>Jun-05</b>		<b>Practical Sound Control (R331)</b>	
460	Apr-05	B basics	Internal Moisture Control (R303, 367)	withdrawn
459	Apr-05	refer 597	Timber Pole House Construction (R352)	withdrawn 31/3/16
458	Feb-05	refer 639	Domestic Fire Protection (R348)	withdrawn 15/8/2018
457	Feb-05	refer 594	Ventilation of Enclosed Subfloor Spaces (R404)	withdrawn 28/1/2016
456	Nov-04	nr	Alternative Solutions	withdrawn 1/01/2015
<b>455</b>	<b>Oct-04</b>	<b>refer 666</b>	<b>Restoring a House After Flood Damage (R308)</b>	<b>withdrawn 1/12/2021</b>
454	Oct-04	nr	Avoiding Thermal Bridging in Steel-Framed Houses	withdrawn 1/05/2015
453	Sep-04	refer 519	Fasteners Selection (R328)	withdrawn 1/02/2010
452	Aug-04	Refer 553, 554	Weatherproofing Aluminium Windows	withdrawn 1/11/2012
451	Aug-04	refer 526	Specifying Timber (R373)	withdrawn 1/08/2010
450	Jan-04	refer 599	Solar-Control Glass Selection and Installation (R297, 298)	withdrawn 1/6/2016
449	Jun-04	nr	Keeping Water out – Timber Framed Walls (R359)	withdrawn 1/01/2015
448	Apr-04	refer 465	Domestic Flashing Installation (R305)	withdrawn 1/09/2005
447	Apr-04	refer 587	Preventing Construction Moisture Problems in New Buildings (R359)	withdrawn 1/07/2015
446	Feb-04	refer 568	Sustainable Construction	withdrawn 1/02/2014
445	Feb-04	refer 493	Timber Treatment (R386)	withdrawn 1/12/2007
<b>444</b>	<b>Dec-03</b>		<b>Lessons from the 1987 Edgcumbe Earthquake (R258)</b>	
443	Dec-03	refer 648	Timber Shingles and Shakes (R288)	withdrawn 30/3/20
442	Oct-03	refer 593	Efflorescence on Masonry (R 268)	withdrawn 28/1/2016
441	Oct-03	refer 601	Sealed Joints in External Claddings - (2) Sealants (R 284)	withdrawn 1/8/2016
440	Oct-03	refer 584	Sealed Joints in External Claddings - (1) Joint Design (R 283)	withdrawn 1/05/2015
439	Aug-03		Condensation Risk in Walls (nr)	withdrawn 1/11/2014
438	Aug-03	refer 675	Using a Scala Penetrometer (R212)	Withdrawn August 2022
437	Jun-03	refer GRG	Dealing with Mould (R67)	withdrawn 1/01/2015
436	Apr-03	refer GPG	Masonry Veneer Construction (R381)	withdrawn 1/07/2007
435	Feb-03		Weathertightness Evaluation	withdrawn 1/11/2013
434	Feb-03	Refer 550	Results of Weathertightness Failure (R338)	withdrawn 1/08/2012
433	Feb-03		Weathertightness Checklist	withdrawn 1/11/2013
432	Dec-02	refer 470	Building Papers and Synthetic Wraps (R336)	withdrawn 1/02/2006
<b>431</b>	<b>Sep-02</b>		<b>Care of Kiln Dried Framing Timber</b>	
430	Sep-02	refer 607	Passive Ventilation	withdrawn 1/2/17
429	Jul-02	refer House Insulation Guide	Calculating R-Values for Timber Framed Walls	withdrawn 1/05/2015
428	Jul-02	nr	Weathertightness Dos and Don'ts	withdrawn 1/01/2015
427	May-02		Improving Thermal Insulation (R334)	withdrawn
426	May-02		Achieving Acoustic Separation (R331 in part)	withdrawn 1/2/2018
425	Apr-02	nr	Finding Leaks	withdrawn 1/01/2015
424	Mar-02	refer 515	Measuring Moisture on Building Sites (R388)	withdrawn 1/10/2009
423	Feb-02	refer 559	Pre-Purchase Inspections	withdrawn 1/04/2013
422	Feb-02	nr	Maintenance and Refurbishments of Aluminium Joinery (R 286)	withdrawn 1/01/2015
421	Dec-01	refer 566	Windows – Films and Coatings	withdrawn 1/12/2013
420	Sep-01	refer 606	Designing for Fire Safety (R307, 309)	withdrawn 1/2/17
419	Sep-01	refer 547	Selecting Glass	withdrawn 1/04/2012
418	Jul-01	refer 531	Providing for Thermal and Moisture Movement (R285)	withdrawn 1/02/2011
417	Jul-01	nr	Maintenance of Concrete Tile Roofs	withdrawn 1/01/2015
416	May-01	refer 468	Fixing Timber Weatherboards	withdrawn 1/12/2005
415	May-01	refer 466	Timber-Framed Parapets, Balustrades and Columns	withdrawn 1/09/2005

**BRANZ Bulletin Index**  
**19 Mar 2024**

414	May-01	nr	Coping With Climate Change	withdrawn 1/01/2015
413	Mar-01	refer GPG Tiling	Substrates for Floor Tiles	withdrawn 19/6/2017
<b>412</b>	<b>Mar-01</b>	<b>pdf only</b>	<b>Concrete Driveways</b>	
<b>411</b>	<b>Apr-01</b>	<b>pdf only</b>	<b>Recommended Timber Cladding Profiles</b>	
410	Jan-01	refer GPG	Selecting Tiles	withdrawn 1/01/2015
409	Jan-01	refer 580	Contracts in the Building Industry	withdrawn 1/01/2015
408	Jan-01	refer 563	Roofs on Exposed Sites (R326)	withdrawn 1/08/2013
407	Jan-01	refer 563	Walls on Exposed Sites (R326)	withdrawn 1/08/2013
406	Nov-00	refer 563	Building on the Coast	withdrawn 1/08/2013
405	Nov-00	refer 563	Timber Framed Buildings on Exposed Sites (R325)	withdrawn 1/08/2013
404	Sep-00	refer 457	Ventilation of Enclosed Subfloor Spaces (R319)	withdrawn 1/02/2005
403	Sep-00	nr	Stucco Mixes	withdrawn 1/01/2015
402	Jul-00	pdf only	Levels of Finish for Flush-Stopped Linings	withdrawn 1/2/2016
401	Jul-00	refer 462	Constructing Timber Decks (R355)	withdrawn 1/07/2005
400	May-00	refer 485	Septic Tanks and Waste Water Systems	withdrawn 1/05/2007
399	May-00	refer 560	Timber Pile Foundations (R267)	withdrawn 1/05/2013
398	Mar-00	refer 530	Straw Bale Construction	withdrawn
397	Mar-00		Waterproofing Basements (R290, 291)	withdrawn
396	Jan-00	nr	Wood-Boring Insects	withdrawn 19/6/2017
395	Jan-00	refer 557	Timber Framed Garages (R354)	withdrawn 1/02/2013
394	Jan-00	refer 562	Low Retaining Walls	withdrawn 1/08/2013
393	Nov-99	nr	Powder-actuated and Mechanically Powered Fastening Tools (279)	withdrawn 1/01/2015
392	Nov-99	refer 487	Swimming Pool Fences	withdrawn 1/08/2007
391	Sep-99	refer 532	Site Records	withdrawn
390	Sep-99	refer 645	Laying Timber Strip Flooring Over Timber Joists	withdrawn 19/6/2017
389	Jul-99	refer 641	Concrete Toppings	withdrawn 31/7/19
388	Jul-99	refer 424	Site Measurement of Moisture in Timber and Concrete	withdrawn 1/03/2002
387	May-99	refer 471	Double Glazing	withdrawn 1/04/2006
386	May-99	refer 445	Timber Treatment (R275)	withdrawn 1/02/2004
<b>385</b>	<b>May-99</b>	<b>pdf only</b>	<b>Asphalt Shingles (R289)</b>	
384	Mar-99		Installing External Doors	withdrawn nr
383	Mar-99	B basics	Reducing Waste from Building Sites	withdrawn 1/11/2013
382	Mar-99	refer 623	Curing Concrete (R269)	withdrawn 1/6/18
381	Jan-99	refer 436	Masonry Veneer Construction (R324)	withdrawn 1/04/2003
380	Jan-99	refer GPG Internal Linings	Timber Internal Linings	withdrawn 19/6/2017
379	Nov-98	nr	Preventing Moisture Problems in Existing Buildings (R272)	withdrawn 1/01/2015
378	Nov-98		Tiling Wet Area Floors	withdrawn nr
377	Nov-98		Maintenance of Painted Steelwork (R253)	withdrawn nr
376	Sep-98		Residential Fire Sprinkler Systems (R262)	withdrawn nr
375	Sep-98		Flashings for Aluminium Windows and Doors	withdrawn nr
374	Sep-98	refer 506	Laying Timber Strip Flooring over Concrete Floor Slabs	withdrawn 1/11/2008
373	Jul-98	refer 451	Specifying Timber (R295)	withdrawn 1/08/2004
372	Jul-98	refer 592	Durability and Crack Control in Domestic Concrete Floor Construction	withdrawn 1/12/2015
371	May-98	refer 628	Particleboard Flooring (R294)	withdrawn 28/9/2018
370	May-98	refer 626	Slip Resistant Floors	withdrawn 27/07/2018
369	Mar-98		Fitting Tolerances	withdrawn 1/8/20
368	Mar-98		Preventing Moisture Problems in Timber Framed Skillion Roofs (R302)	withdrawn 1/06/2007
367	Mar-98	refer 460	Condensation (R278)	withdrawn 1/04/2005
366	Jan-98	refer 463	Installing Aluminium Windows and Doors	withdrawn 1/07/2005
365	Jan-98	refer 505	Acceptable Plans and Specifications	withdrawn 1/11/2008
<b>364</b>	<b>Jan-98</b>	<b>PDF only</b>	<b>Preventing Noise in Plumbing Installations</b>	
363	Jan-98	refer 535	Repairing Cracks in Concrete (R231)	withdrawn 1/06/2011
362	Oct-97	refer 638	Finishes on Architectural Hardware (R249)	withdrawn 1/6/2019
361	Oct-97	nr	Weathergrooves (280)	withdrawn 19/6/2017
360	Aug-97	refer 646	Floor Levelling Compounds (R123)	withdrawn 1/2/2020
359	Aug-97	refer 447	Preventing Moisture Problems in New Buildings (R272)	withdrawn 1/04/2004
358	Jun-97	New GPG	Crest Fixing of Profiled Metal Roofing (R235)	withdrawn 1/11/2013
357	Jun-97	refer 494, 496	Thermal Insulation of Houses (R292)	withdrawn 1/02/2008

**BRANZ Bulletin Index**  
**19 Mar 2024**

356	Apr-07	nr	Adhesives for Use with Wood and Wood-based Products (R246)	withdrawn 1/01/2015
355	Apr-97	refer 401	Timber Decks	withdrawn 1/07/2000
354	Feb-97	refer 395	Garage Design	withdrawn 1/01/2000
353	Feb-97	refer 570	Ground Clearances	withdrawn 1/03/2014
352	Dec-96	refer 459	Pole House Construction (R232)	withdrawn 1/04/2005
351	Dec-96	refer 464	Preventing Corrosion of Reinforcing Steel in Concrete (R226)	withdrawn 1/07/2005
350	Oct-96	refer 509	Sizing Gutters and Downpipes (R251)	withdrawn
349	Aug-96	refer 634	Finishes for Aluminium (213, 218)	withdrawn 1/02/2019
348	Jul-96	refer 458	Domestic Smoke Alarms (R252)	withdrawn 1/02/2005
347	Jul-96		Using Kiln-Dried MSG Radiata Pine Framing	withdrawn 1/04/2007
346	Jun-96		Flat Membrane Roofs - Materials	withdrawn 1/01/2015
345	Jun-96	no repl	Flat Membrane Roofs - Design and Installation	withdrawn 7/10/2013
344	Apr-96	refer 491	Embedded Floor Heating (R 293)	withdrawn 1/10/2007
343	Apr-96		Moisture in Timber (R271)	withdrawn
342	Feb-96		External Insulation and Finish Systems (R 287)	withdrawn 1/10/2001
341	Feb-96	nr	Protecting Valuable Records	withdrawn 1/01/2015
340	Feb-96	refer 520	Conservatories (R276)	withdrawn
339	Dec-95	refer tile GPG	Internal Wall Tiling	withdrawn 1/10/1996
338	Dec-95	refer 434	Rot in Timber	withdrawn 1/04/2003
337	Oct-95	refer 636	Protecting Window Glass from Surface Damage (R 236)	withdrawn 1/04/2019
336	Aug-95	refer 432	Building Papers, Wind Barriers and Vapour Barriers (R277)	withdrawn 1/06/2005
335	-1995	nr	Exposed Aggregate Precast Concrete Panels (R260)	withdrawn 1/01/2015
334	-1995	refer 427	Reducing Heat Losses From Existing Houses (R201)	withdrawn 1/05/2002
333	-1995	refer 469	Damp-proof Membranes to Concrete Slabs (R 274)	withdrawn 1/02/2006
332	-1995		Claddings in Corrosive Environments	withdrawn nr
331	-1995	refer 426, 461	Practical Sound Control (R180, 210, 211)	withdrawn 1/06/2005
330	-1995		Thin Flooring Materials- (2) Preparation and Laying (R 223)	withdrawn Dec 13 approx
329	-1995		Thin Flooring Materials - (1) Selection and Maintenance (R 222)	withdrawn Dec 13 approx
328	-1994	refer 453	Selection and Use of Fasteners	withdrawn 1/09/2004
327	-1994	nr	Open Fireplaces and Chimneys (R192)	withdrawn 19/6/2017
326	-1994	refer 407, 408	Cladding Buildings on Exposed Sites	withdrawn 1/01/2001
325	-1994	refer 405	Timber Framed Buildings on Exposed Sites (R 207)	withdrawn 1/11/2000
324	-1994	refer 381	Masonry Veneer Cladding - Detailing and Construction (R 94)	withdrawn 1/01/1999
323	-1994	nr	Glazing Plastics - (2) Design and Fixing (R 242)	withdrawn 30/11/17
322	-1994	nr	Glazing Plastics - (1) Types and Durability (R 241)	withdrawn 30/11/17
321	-1994	refer 620	Reducing the Impact of Wind at Building Sites (R 191)	withdrawn 10/4/2018
320	-1995	refer 495	Stair Design and Safety (R 256)	withdrawn 1/02/2008
319	-1994	refer 404	Subfloor Ventilation (R 245)	withdrawn 1/09/2000
318	-1994	refer 595	Care of Coil-Coated Metal Claddings (R 263)	withdrawn 28/1/2016
317	-1994	refer 488	Coil-coated Metal Claddings (R 261)	withdrawn 1/08/2007
316	-1993		Timber Strip Flooring and Internal Linings (R 170)	withdrawn nr
315	-1993		Wood Primers (R 257)	withdrawn nr
314	-1993	refer 633	Removing Paint From Houses	withdrawn 1/02/2019
313	-1993	refer 605	Domestic Glazing Safety	withdrawn 1/12/2016
312	-1993	pdf only	Reducing Heat Loss Through Windows. (R 224)	withdrawn
311	-1993	Refer 540	Use and Control of Solar Gain	withdrawn 1/10/2011
310	not issued			
309	-1993	refer 420	Fire Safety in Dwellings	withdrawn 1/09/2001
308	-1993	refer 455	Restoring a House After Flood Damage (R240)	withdrawn 1/11/2004
307	-1993	refer 420	Designing for Fire Safety (R 200)	withdrawn 1/09/2001
306	-1993	refer 654	Inspection Procedures for Chimneys, Fireplaces and Solid Fuel Appliances (R259)	withdrawn 1/10/2020
305	-1993	refer 448	Domestic Flashing Installation	withdrawn 1/04/2004
304	-1993	refer 467	Flashing Design	withdrawn 1/12/2005
303	-1992	refer 460	Moisture Control in Recreational Facilities	withdrawn 1/04/2005
302	-1992	refer 368	Constructing Timber Framed Skillion Roofs (R 111, 112, 113)	withdrawn 1/03/1998
301	-1993	refer GPG Internal Linings	Preventing Peaking and Popping Problems with Gypsum Plaster Board	withdrawn 19/6/2107
300	-1992		Plastic Piping - Installation	withdrawn nr

**BRANZ Bulletin Index**  
**19 Mar 2024**

299	-1992		<i>Plastic Piping - Types and Properties</i>	<i>withdrawn nr</i>
298	-1992	refer 450	<i>Solar Control Glass - Design and Installation Practice (R 265)</i>	<i>withdrawn 1/06/2004</i>
297	-1992	refer 450	<i>Solar Control Glass - Types and Properties (R 264)</i>	<i>withdrawn 1/06/2004</i>
296	-1992		<i>Transparent and Semi-transparent Exterior Finishes for Timber Exposed to the Weather (R 273)</i>	<i>withdrawn nr</i>
295	-1992	refer 373	<i>Specifying Timber (R 130)</i>	<i>withdrawn 1/07/1998</i>
294	-1992	refer 371	<i>Reconstituted Wood Board Sheet Flooring</i>	<i>withdrawn 1/05/1998</i>
293	-1992	refer 344	<i>Embedded Electric Floor Heating (R 179)</i>	<i>withdrawn 1/04/1996</i>
292	-1992	refer 357	<i>Thermal Insulation of Houses (R 169, 217, 233)</i>	<i>withdrawn 1/06/1997</i>
291	-1992	refer 397	<i>Basement Waterproofing - Selecting An Appropriate Membrane (R 38)</i>	<i>withdrawn 1/03/2000</i>
290	-1992	refer 397	<i>Basement Waterproofing - Design Principles (R 37)</i>	<i>withdrawn 1/03/2000</i>
289	-1992	refer 385	<i>Asphalt Shingle Roofing</i>	<i>withdrawn 1/05/1999</i>
288	-1992		<i>Timber Shingle and Shake Roofing</i>	<i>withdrawn 1/12/2003</i>
287	-1991	refer 342	<i>External Insulation and Finish Systems</i>	<i>withdrawn 1/02/1996</i>
286	-1991	refer 422	<i>Aluminium Windows – Design, Handling and Maintenance (R 225)</i>	<i>withdrawn 1/02/2002</i>
285	-1991	refer 418	<i>Designing for Thermal and Moisture Movement (R 70)</i>	<i>withdrawn 1/07/2001</i>
284	-1991	refer 441	<i>Sealed Joints in External Claddings - (2) Sealants (R 239)</i>	<i>withdrawn 1/10/2003</i>
283	-1991	refer 440	<i>Sealed Joints in External Claddings - (1) Joint Design (R 238)</i>	<i>withdrawn 1/10/2003</i>
282	-1991		<i>Glass Blocks - Materials and Installation</i>	<i>withdrawn nr</i>
281	-1991		<i>Glass Blocks - Selection and Design</i>	<i>withdrawn nr</i>
280	-1991	refer 361	<i>Weathergrooves</i>	<i>withdrawn 1/10/1997</i>
279	-1991	refer 393	<i>Powder-Powered Fastening Devices (R 149)</i>	<i>withdrawn 1/11/1999</i>
278	-1991	refer 367	<i>Preventing Dampness in Houses (R 243, 244)</i>	<i>withdrawn 1/03/1998</i>
277	-1991	refer 336	<i>Building Papers, Vapour Barriers and Wind Barriers (R125, 155)</i>	<i>withdrawn 1/08/1995</i>
276	-1991	refer 340	<i>Conservatories</i>	<i>withdrawn 1/02/1996</i>
275	-1990	refer 386	<i>Timber Treatment for Users and Specifiers (R 175)</i>	<i>withdrawn 1/05/1999</i>
274	-1990	refer 333	<i>Damp-proof Membranes to Concrete Slabs</i>	<i>withdrawn?? 95</i>
273	-1990	refer 296	<i>Transparent and Semi-transparent Exterior Finishes for Timber Exposed to the Weather (R 273)</i>	<i>withdrawn??92</i>
272	-1990	refer 359, 379	<i>Moisture in the Building Structure (R 215)</i>	<i>withdrawn 1/08/1997</i>
271	-1990	refer 343	<i>Changes in Moisture Content in Timber (R 25)</i>	<i>withdrawn 1/04/1996</i>
270	-1990		<i>Human Impact on Glass in High Rise Buildings</i>	<i>withdrawn</i>
269	-1990	refer 382	<i>Curing of Concrete (The) (R 59)</i>	<i>withdrawn 1/03/1999</i>
268	-1990	refer 442	<i>Efflorescence on Masonry (R32)</i>	<i>withdrawn 1/12/2003</i>
267	-1989	refer 399	<i>Timber Pile Foundations for Single Storey Light Timber Framed Buildings</i>	<i>withdrawn 1/05/2000</i>
266	-1989	refer Good Tiling	<i>Exterior Ceramic Wall Tiling</i>	<i>withdrawn</i>
265	-1989	refer 298	<i>Solar Control Glass - Design and Installation Practice</i>	<i>withdrawn</i>
264	-1989	refer 297	<i>Solar Control Glass - Types and Properties</i>	<i>withdrawn</i>
263	-1989	refer 318	<i>Care of Coil-Coated Metal Claddings</i>	<i>withdrawn</i>
262	-1989	refer 376	<i>Residential Fire Sprinklers</i>	<i>withdrawn 1/09/1998</i>
261	-1989	refer 317	<i>Coil-Coated Metal Claddings</i>	<i>withdrawn</i>
260	-1988	refer 335	<i>Exposed Aggregate Precast Concrete Panels</i>	<i>withdrawn</i>
259	-1988	refer 306	<i>Inspection Procedures for Chimneys, Fireplaces and Solid Fuel Burning Appliances</i>	<i>withdrawn</i>
258	-1987	refer 444	<i>Lessons From the 1987 Edgecumbe Earthquake</i>	<i>withdrawn 1/12/2003</i>
257	-1987	refer 315	<i>Wood Primers</i>	<i>withdrawn</i>
256	-1987	refer 320	<i>Stair Design and Safety</i>	<i>withdrawn</i>
255	-1987		<i>Polymer Concrete Floors</i>	<i>withdrawn</i>
254	-1987	refer 332	<i>Avoiding Corrosion Problems in Buildings</i>	<i>withdrawn</i>
253	-1987	refer 377	<i>Maintenance Painting of Coated Steel Structures</i>	<i>withdrawn 1/11/1998</i>
252	-1987	refer 348	<i>Domestic Smoke Alarms</i>	<i>withdrawn 1/07/1996</i>
251	-1986	refer 350	<i>Gutters and Downpipes (R140)</i>	<i>withdrawn 1/10/1996</i>
250	-1986		<i>Testing for Fire Resistance</i>	<i>withdrawn</i>
249	-1986	Refer 362	<i>Finishes on Architectural Hardware</i>	<i>withdrawn 1/10/1997</i>
248	-1986		<i>Solid Fuel Appliances: Their Use in Existing Fireplaces</i>	<i>withdrawn</i>
247	(1985, 86)		<i>Solid Fuel Stoves</i>	<i>withdrawn</i>
246	-1985	refer 356	<i>Adhesives for Use with Wood and Wood-based Products</i>	<i>withdrawn 1/06/1997</i>
245	-1985	refer 319	<i>Subfloor Ventilation</i>	<i>withdrawn</i>



**BRANZ Bulletin Index**  
**19 Mar 2024**

244	-1985	refer 278	Preventing Dampness in Houses 2: Condensation and Mildew (R216)	withdrawn
243	-1985	refer 278	Preventing Dampness in Houses 1: Underfloor Dampness	withdrawn
242	-1985	refer 323	Glazing Plastics 2: Design and Fixing	withdrawn
241	-1985	refer 322	Glazing Plastics 1: Types and Durability	withdrawn
240	-1984	refer 308	Restoring a House after Flood Damage	withdrawn
239	-1984	refer 284	Sealed Joints in External Claddings 2 - Sealants	withdrawn
238	-1984	refer 283	Sealed Joints in External Claddings 1 Joint Design	withdrawn
237	-1984	refer 338	Dry Rot in Timber (R17)	withdrawn
236	-1984	refer 337	Corrosion and Staining of Glass Windows	withdrawn
235	-1984	refer 358	Nail Fixing of Corrugated Steel Roofing	withdrawn 1/06/1997
234	-1983	refer 261	Coil-Coated Products: Information for Designers	withdrawn
233	-1983	refer 292	Insulating Suspended Timber Frame Floors	withdrawn
232	-1989	refer 352	Pole House Construction (1989)	withdrawn 1/12/1996
231	-1982	refer 363	Repairing Cracks in Concrete (R36)	withdrawn 1/01/1998
230	-1982		Stainless Steels for Building Claddings	withdrawn
229	-1981		Glass Fibre-reinforced Polyester Cladding Panels 2 Design, Durability and Maintenance	withdrawn
228	-1981		Glass Fibre-reinforced Polyester Cladding Panels 1 Materials and Manufacture	withdrawn
227	-1981		Weights and Sizes of Building Materials	withdrawn
226	-1981	refer 351	Corrosion of Reinforcing Steel	withdrawn 1/12/1996
225	-1981	refer 286	Aluminium Windows Do's and Don'ts	withdrawn
224	-1980	refer 312	Double Glazing	withdrawn
223	-1980	refer 330	PVC Flooring 2 Preparation and Laying (R 92)	withdrawn
222	-1980	refer 329	PVC Flooring 1 - Materials and Maintenance (R 92)	withdrawn
221	-1980	refer Good Tiling	Ceramic Tiled Floors - (2) Laying (R 73)	withdrawn
220	-1980	refer Good Tiling	Ceramic Tiled Floors - (1) Materials and Maintenance (R73)	withdrawn
219	-1980		Single Stack Drainage	withdrawn
218	(1979, 84)	refer 349	Use of Powder-coated Aluminium	withdrawn 1/08/1996
217	(1979, 81)	refer 292	Thermal Insulation of Houses	withdrawn
216	-1979	refer 272	Condensation (R109)	withdrawn
215	(1979	refer 272	Moisture Control in Buildings	withdrawn
214	-1979		Protection of Galvanised Steel Claddings	withdrawn
213	-1979	refer 349	Use of Anodised Aluminium	withdrawn 1/08/1996
212	-1979	refer 438	Soil Testing (with the Scala Penetrometer)	withdrawn 1/08/2003
211	-1978	refer 331	Noise Control in Flats - 2	withdrawn
210	-1978	refer 331	Noise Control in Flats - 1	withdrawn
209	-1978		Management Assistance for Small Companies	withdrawn
208	-1978	refer 257	Wood Primers	withdrawn
207	-1978	refer 325	Building on Windswept Sites	withdrawn
206	-1978	refer 232	Pole Frame Construction	withdrawn
205	(1978, 84)		Concrete Do's and Don'ts	withdrawn
204	-1978		CI/SfB Information Classification System	withdrawn
203	-1978	refer 332	Atmospheric Corrosion of Metals	withdrawn
202	-1978	refer 254	Avoiding Corrosion Problems in Buildings	withdrawn
201	-1977	refer 334	Reducing Heat Losses From Existing Houses	withdrawn
200	-1977	refer 307	Fire and Buildings - Control of Fire by Building Design	withdrawn
199	-1977		Case Histories	withdrawn
198	-1977		Fire and Buildings - Terminology and tests	withdrawn
197	-1977	refer 197A	Solar Water Heaters Installation	withdrawn
196	(1977, 79)		Solar Water Heaters Application	withdrawn
195	-1977	refer 207	Building on Windswept Sites	withdrawn
194	-1977		Weather and the Builder	withdrawn
193	(1976, 79)		Fireside Topics	withdrawn
192	-1977	refer 327	Open Fireplaces and Chimneys	withdrawn
191	(1976, 81)	refer 321	Wind - Selecting and Protecting a Site (R16)	withdrawn
190	-1976		Solar Control Glass Case Histories	withdrawn
189	(1976, 79)	refer 215	Moisture Control in Buildings	withdrawn
188	-1976	refer 265	Solar Control Glass Installation Practice	withdrawn
187	-1976		Storm Damage	withdrawn
186	-1976		Case Histories	withdrawn

**BRANZ Bulletin Index**  
**19 Mar 2024**

185	-1976		<i>Index to Bulletins</i>	<i>withdrawn</i>
184	-1976	<i>refer 227</i>	<i>Weights and Sizes of Building Materials</i>	<i>withdrawn</i>
183	(1976,79)		<i>Plumbing Do's and Don'ts</i>	<i>withdrawn</i>
182	-1976	<i>refer 217</i>	<i>Thermal Insulation of Houses</i>	<i>withdrawn</i>
181	-1975		<i>Control of Shower Temperature Fluctuations</i>	<i>withdrawn</i>
180	(1975, 78)	<i>refer 331</i>	<i>Acoustic Performance Requirements of Partitions</i>	<i>withdrawn</i>
179	-1975	<i>refer 293</i>	<i>Embedded Electric Floor Heating (R79)</i>	<i>withdrawn</i>
178	-1975		<i>Do's and Don'ts</i>	<i>withdrawn</i>
177	-1975	<i>refer 233</i>	<i>Building Foil Insulated Floors</i>	<i>withdrawn</i>
176	-1974	<i>refer 294</i>	<i>Particle Board Flooring</i>	<i>withdrawn</i>
175	-1974	<i>refer 275</i>	<i>Timber Preservation for the User</i>	<i>withdrawn</i>
174	-1974		<i>Metrication 3</i>	<i>withdrawn</i>
173	-1973		<i>Falls on Building Sites</i>	<i>withdrawn</i>
172	-1973		<i>Plywood Flooring</i>	<i>withdrawn</i>
171	-1973		<i>Stainless Steel Water Tanks</i>	<i>withdrawn</i>
170	-1973	<i>refer 316</i>	<i>Timber Vertical Boarding</i>	<i>withdrawn</i>
169	-1973	<i>refer 292</i>	<i>Correct Use of Foil Insulation in Walls (The)</i>	<i>withdrawn</i>
168	-1973		<i>Squeaky Floors</i>	<i>withdrawn</i>
167	-1973		<i>Corrosion of Copper Pipe in Housing</i>	<i>withdrawn</i>
166	-1973		<i>On-Site Precasting - Tilt up Part 2</i>	<i>withdrawn</i>
165	-1973		<i>On-Site Precasting - Tilt up Part 1</i>	<i>withdrawn</i>
164	-1973		<i>Cost of Labour (The)</i>	<i>withdrawn</i>
163	(1973, 78)		<i>Sound Absorbers and their Use</i>	<i>withdrawn</i>
162	-1973		<i>Joists, Floor Beams and Lintels for Small Buildings</i>	<i>withdrawn</i>
161	(1972, 80)		<i>Formwork Release Agents</i>	<i>withdrawn</i>
160	-1972		<i>Index to Bulletins</i>	<i>withdrawn</i>
159	-1972		<i>Pumping Concrete</i>	<i>withdrawn</i>
158	(1972, 78)	<i>refer 239</i>	<i>Putties Mastics and Sealants 2</i>	<i>withdrawn</i>
157	(1972, 78)	<i>refer 238</i>	<i>Putties Mastics and Sealants 1</i>	<i>withdrawn</i>
156	-1972		<i>Change to Metric in the Building Industry</i>	<i>withdrawn</i>
155	-1972	<i>refer 277</i>	<i>Building Papers and Membranes</i>	<i>withdrawn</i>
154	(1972, 80)		<i>Plastering (3) Internal Walls and Ceilings</i>	<i>withdrawn</i>
153	-1972		<i>Design for Mass Housing</i>	<i>withdrawn</i>
152	(1972, 77)		<i>Concrete Ground Floor Slabs</i>	<i>withdrawn</i>
151	-1972		<i>Timber Formwork for Concrete</i>	<i>withdrawn</i>
150	-1972		<i>Building Bylaws and Regulations</i>	<i>withdrawn</i>
149	-1971	<i>refer 279</i>	<i>Powder-Powered Tools</i>	<i>withdrawn</i>
148	-1971		<i>How to Keep Comfortable in Buildings</i>	<i>withdrawn</i>
147	-1971		<i>Plastering 2 - External Walls</i>	<i>withdrawn</i>
146	-1971	<i>refer 214</i>	<i>Galvanised Corrugated Steel and its Protection</i>	<i>withdrawn</i>
145	-1971		<i>Plastering 1 - General Practices and Problems</i>	<i>withdrawn</i>
144	-1971		<i>Do's and Don'ts No 7</i>	<i>withdrawn</i>
143	-1971		<i>Good Lighting in Buildings</i>	<i>withdrawn</i>
142	-1971	<i>refer 324</i>	<i>Masonry Veneer Construction</i>	<i>withdrawn</i>
141	-1971	<i>refer 204</i>	<i>CI/SfB Information Classification System</i>	<i>withdrawn</i>
140	-1971	<i>refer 251</i>	<i>Gutters Spouting and Downpipes</i>	<i>withdrawn</i>
139	-1971		<i>Concrete Floor Finishes and Toppings</i>	<i>withdrawn</i>
138	-1971		<i>Metric Conversion</i>	<i>withdrawn</i>
137	-1970		<i>Metric Conversion</i>	<i>withdrawn</i>
136	-1970		<i>Surface Spread of Flame</i>	<i>withdrawn</i>
135	-1970		<i>Wind Loads: Some Problem and Design Aspects</i>	<i>withdrawn</i>
134	-1970		<i>CPM: Building and Construction Some Useful Developments</i>	<i>withdrawn</i>
133	-1970		<i>CPM fro Building and Construction Management</i>	<i>withdrawn</i>
132	-1970		<i>Acoustic Insulation Properties of Partitions in Buildings</i>	<i>withdrawn</i>
131	-1970		<i>Care of Materials on Site</i>	<i>withdrawn</i>
130	(1970, 77)	<i>refer 295</i>	<i>Specifying Timber - Species and Grade</i>	<i>withdrawn</i>
129	-1970		<i>Timber Shrinkage in New Buildings</i>	<i>withdrawn</i>
128	-1970		<i>Continuity of Publication</i>	<i>withdrawn</i>
127	-1970		<i>Concrete Blocks for Houses</i>	<i>withdrawn</i>
126	-1970		<i>External Walls: Principles and Practice</i>	<i>withdrawn</i>
125	-1969	<i>refer 277</i>	<i>Vapour Barriers</i>	<i>withdrawn</i>
124	-1969		<i>Fire Resistance Ratings</i>	<i>withdrawn</i>

**BRANZ Bulletin Index**  
**19 Mar 2024**

123	-1969	refer 360	Level Surfaces on Concrete Floors under Thin Flooring	withdrawn 1/08/1997
122	-1969	refer 219	Single Stack Drainage	withdrawn
121	-1969	refer 249	Metal Hardware Finishes	withdrawn
120	-1969		Thermal Resistance	withdrawn
119	-1969		Recommendations for the Painting of Buildings	withdrawn
118	-1969	refer 176	Particle Board Flooring	withdrawn
117	-1969		Metric System (The)	withdrawn
116	-1969		Masonry Cladding	withdrawn
115	-1969		Organic Surface Coatings	withdrawn
114	-1969	refer 216	Risk of Condensation (The) (R109)	withdrawn
113	-1968	refer 302	Sloping Compact Roofs	withdrawn
112	(1968, 77)	refer 302	Flat Compact Roofs - Practice	withdrawn
111	(1968, 77)	refer 302	Flat Compact Roofs - Problems	withdrawn
110	-1968		Vapour Diffusion	withdrawn
109	-1968	refer 216	Condensation	withdrawn
108	-1968		Accuracy and Tolerances - Part 3	withdrawn
107	-1968		Accuracy and Tolerances - Part 2	withdrawn
106	-1968		Accuracy and Tolerances - Part 1	withdrawn
105	-1968		Pitched Roofs Performance Requirements	withdrawn
104	-1968		Sources of Electric Light	withdrawn
103	-1968		Airflow Around Buildings	withdrawn
102	-1968		Solar Water Heating for Domestic Use	withdrawn
101	-1967		Lightweight Concrete 6 - Sawdust Concrete	withdrawn
100	(1967, 77)		Availability of Daylight for Building Design	withdrawn
99	-1967		Lightweight Concrete 5 Artificial Aggregates - Perlite	withdrawn
98	-1967		Gypsum Products - Their Behaviour in Fire	withdrawn
97	-1967		Lightweight Concrete 4 Artificial Aggregates - Vermiculite	withdrawn
96	-1967		Lightweight Concrete 3 No-fines Concrete	withdrawn
95	-1967		Weatherproof Jointing	withdrawn
94	(1967, 77)	refer 142	Cavity Wall Construction	withdrawn
93	-1967		Glazing Design	withdrawn
92	-1967	refer 222,223	PVC Flooring (R22)	withdrawn
91	-1967		Solar Radiation Through Vertical Glass	withdrawn
90	-1967		Do's and Don'ts No 6	withdrawn
89	-1966		Battery Casting of Concrete Panels	withdrawn
88	-1966		Lightweight Concrete 2 - Pumice Concrete	withdrawn
87	-1966	refer 299, 300	Unplasticised PVC Pipe	withdrawn
86	-1966		Lightweight Concrete 1 - Aerated Concrete	withdrawn
85	-1966		House Construction - Critical Path Planning	withdrawn
84	-1966		Do's and Don'ts No 5	withdrawn
83	-1966	refer 331	Practical Noise Control for Timber Framed Buildings	withdrawn
82	-1966		Internal Wood Flooring Naturally Finished	withdrawn
81	-1966		Behaviour of Curtain Walling in Fire (The)	withdrawn
80	-1966	refer 230	Stainless Steel for Buildings	withdrawn
79	-1966	refer 293	Electric Floor Heating – 2 (R24)	withdrawn
78	-1966		Do's and Don'ts No 4	withdrawn
77	-1965		Uses of Lime in Buildings - 2 (The)	withdrawn
76	-1965		Uses of Lime in Buildings - 1 (The)	withdrawn
75	-1965	refer 359	Rain Penetration	withdrawn
74	-1965		Mastics and Gaskets	withdrawn
73	-1965	refer 220, 221	Ceramic Tiled Floors	withdrawn
72	-1965		Do's and Don'ts No 3	withdrawn
71	-1965	refer 182	Thermal Insulation of Houses	withdrawn
70	-1965	refer 285	Dimensional Changes in Building Materials	withdrawn
69	-1965	refer 94	Damp-Course for Masonry Walls (A)	withdrawn
68	-1965		Mould Stains on Timber	withdrawn
67	-1965	refer 437	Mould in Dwellings	withdrawn 1/06/2003
66	-1965		Concrete Admixtures	withdrawn
65	-1964		Sound Insulating Floors in Buildings - 1	withdrawn
64	-1964	refer 246	Adhesives for the Building Industry	withdrawn
63	-1964		Design of Modern Kitchens (The)	withdrawn
62	-1964		Wire Nails for Building Purposes	withdrawn

**BRANZ Bulletin Index**  
**19 Mar 2024**

61	-1964		<i>Roof Vents for the Control of Fire</i>	<i>withdrawn</i>
60	-1964		<i>Isolating Transformers</i>	<i>withdrawn</i>
59	-1964	refer 269	<i>Curing of Concrete (The)</i>	<i>withdrawn</i>
58	-1964	refer 316	<i>Timber Flooring</i>	<i>withdrawn</i>
57	-1964		<i>Do's and Don'ts No 2</i>	<i>withdrawn</i>
56	-1964		<i>Trade Literature for the Building Industry: Its Classification and Storage</i>	<i>withdrawn</i>
55	-1964		<i>Metal Roofing Systems</i>	<i>withdrawn</i>
54	-1964		<i>Electric Wiring Regulations 1961</i>	<i>withdrawn</i>
53	-1963		<i>Wood Screws</i>	<i>withdrawn</i>
52	-1963		<i>Silicone Water Repellents</i>	<i>withdrawn</i>
51	-1963		<i>Do's and Don'ts</i>	<i>withdrawn</i>
50	(1963, 66)		<i>Model Building Bylaw (The)</i>	<i>withdrawn</i>
49	-1963	refer 260	<i>Exposed Aggregate Facing Panels</i>	<i>withdrawn</i>
48	-1963		<i>House Foundations on Unstable Soil</i>	<i>withdrawn</i>
47	-1963		<i>Noise Control Within a Room</i>	<i>withdrawn</i>
46	(1963, 66)		<i>Built-up Roofing</i>	<i>withdrawn</i>
45	(1963, 66)		<i>Fair Face Finish to Concrete</i>	<i>withdrawn</i>
44	(1963, 66)		<i>Formwork for Concreting</i>	<i>withdrawn</i>
43	-1963		<i>Permanent Supplementary Lighting in Offices</i>	<i>withdrawn</i>
42	(1963, 66)		<i>Plumbing for Tall Buildings</i>	<i>withdrawn</i>
41	(1962, 66)		<i>Mis-use of Metals in Buildings: Corrosion (The)</i>	<i>withdrawn</i>
40	-1962	refer 143	<i>Good Lighting in Buildings</i>	<i>withdrawn</i>
39	-1962	refer 145, 147	<i>Plastering on Concrete</i>	<i>withdrawn</i>
38	(1962, 66)	refer 291	<i>Waterproofing of Basements (Tanking) - 2</i>	<i>withdrawn</i>
37	(1962, 66)	refer 290	<i>Waterproofing of Basements (Tanking) - 1</i>	<i>withdrawn</i>
36	-1962	refer 231	<i>Repairing Cracks in Concrete</i>	<i>withdrawn</i>
35	-1962		<i>Recommended Glazing Sizes in High Winds (R22)</i>	<i>withdrawn</i>
34	-1962		<i>Warm Air Curtains</i>	<i>withdrawn</i>
33	-1962	refer 142	<i>Masonry Veneer Construction</i>	<i>withdrawn</i>
32	-1962	refer 268	<i>Efflorescence of Masonry</i>	<i>withdrawn</i>
31	(1962, 66)		<i>Plastic Formwork for Concrete</i>	<i>withdrawn</i>
30	-1962		<i>Building Materials and Fire</i>	<i>withdrawn</i>
29	-1961	refer 132	<i>Sound Insulating Partitions in Buildings</i>	<i>withdrawn</i>
28	-1961		<i>Building Research in Australia</i>	<i>withdrawn</i>
27	(1961, 77)		<i>Domestic Electric Power Supply</i>	<i>withdrawn</i>
26	(1961, 66)	refer 92	<i>Floor Coverings on Concrete Slabs</i>	<i>withdrawn</i>
25	(1961, 66)	refer 271	<i>Changes in the Moisture Content of Timber</i>	<i>withdrawn</i>
24	-1961	refer 79	<i>Electric Floor Heating</i>	<i>withdrawn</i>
23	(1961, 66)	refer 274	<i>Dampproof Membranes to Concrete Slabs</i>	<i>withdrawn</i>
22	-1961	refer 35	<i>Safe Glazing Sizes in High Wind</i>	<i>withdrawn</i>
21	-1961		<i>Finishing of Concrete Floors (The)</i>	<i>withdrawn</i>
20	(1961, 66)		<i>Present Day Paint and its Use</i>	<i>withdrawn</i>
19	-1966		<i>Good Concrete for the Small Builder</i>	<i>withdrawn</i>
18	(1961, 66)	refer 191	<i>Beware of the Wind</i>	<i>withdrawn</i>
17	(1960, 77)	refer 237	<i>Dry Rot in Timber</i>	<i>withdrawn</i>
16	(1960, 66)	refer 217	<i>Thermal Insulation for Buildings</i>	<i>withdrawn</i>
15	-1960	refer 215	<i>Dampness in Buildings</i>	<i>withdrawn</i>
14	(1960, 66)	refer 206	<i>Paint Protection of Iron and Steel against Corrosion</i>	<i>withdrawn</i>
13	-1960		<i>Fire Protection of Buildings</i>	<i>withdrawn</i>
12	(1960, 66)	refer 140	<i>Spouting and Downpiping</i>	<i>withdrawn</i>
11	-1960	refer 225	<i>Glazing into Aluminium</i>	<i>withdrawn</i>
10	-1960	refer 224	<i>Double Windows</i>	<i>withdrawn</i>
9	(1960, 66)	refer 214	<i>Galvanised Corrugated Roofing Iron</i>	<i>withdrawn</i>
8	-1960	refer 155	<i>Waterproof Building Papers</i>	<i>withdrawn</i>
7	(1960, 66)	refer 273	<i>Clear Finishes for External Timberwork</i>	<i>withdrawn</i>
6	-1960	refer 175	<i>Timber Preservation for the User</i>	<i>withdrawn</i>
5	-1966		<i>Fire Hazards with Slow Combustion Stove Installation</i>	<i>withdrawn</i>
4	-1966		<i>Aids to Concreting</i>	<i>withdrawn</i>
3	(1959, 66)		<i>Use of Radiata Pine in Construction (The)</i>	<i>withdrawn</i>
2	-1959	refer 286	<i>Aluminium Window Frames</i>	<i>withdrawn</i>
1	-1959		<i>New Materials a Cautionary Tale</i>	<i>withdrawn</i>

**BRANZ Bulletin Index**  
**19 Mar 2024**

--	--	--	--	--

**BRANZ Bulletin Index**  
**19 Mar 2024**